



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CHUAN LIM CONSTRUCTION PTE LTD
20 SENOKO DR
SINGAPORE 758207
Insured CHUAN LIM CONSTRUCTION PTE LTD
Policy GA581143/1

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 25/1/2022

Our Case Ref. SC22/01/010/4CL-TP

Accident Date 25/1/2022

Damaged Vehicle No: SKV3556Y

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	REAR BUMPER X ⁿⁿ	1 PC	\$960.00	-	\$960.00 X
2	REAR BUMPER SPOILER cut-	1 PC	\$270.00	10% ²⁴³	\$243.00 X
3	REVERSE SENSOR ? X ⁿⁿ	1 PC	\$225.00	-	\$225.00 X
4	TOWING COVER X ⁿⁿ	1 PC	\$50.00	-	\$50.00 X
Labour Charges					
1	LABOUR FOR REAR PORTION	1	\$1,280.00	250/-	\$1,030.00
2	LABOUR FOR WIRING	1	\$80.00	40/-	\$40.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
243 250 40 533 Ram Hp 90010068 1 day 22/03/22 @ 1025 P/P Reay after repair					Sub Total S 2,865.00

Authorised Signature