



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22001042/Evy3n2 Date: 29/03/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YN 2040B
	Policy No.	Z21VC05009610	Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025419	Excess (\$)	3,700.00
	Assign From	GERALD POH	Assign Date	03/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HINO FD8JPKA	c.c	7684
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	FD8JPK12162	Colour	WHITE
	Odometer	280325 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm
	R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm
	L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	04/02/2022
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
5a. Remarks				
	A)THE MARKET VALUE IS S\$108,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	