

Shiau Chan (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 9 February 2022 2:37 PM
To: Shiau Chan (LKKAuto)
Subject: FW: GBF 9147X

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: mttan <mttan@kanfs.net>
Sent: Wednesday, 9 February 2022 1:47 PM
To: Naz (LKKAuto) <Naz@lkkauto.com>
Cc: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Henry Pakianathan (AIG) <henry.pakianathan@aig.com>; Priscilla-LK.Sim@aig.com; Kok-Chong.Lim@aig.com
Subject: Re: GBF 9147X

Dear LKK Team

The Damage extend is bad and not parts available in our local market(there might be hidden parts upon dismantling)

Therefore we are unable to repair the vehicle at the limited sum of \$20k

Thank you

Mr Tan
KFS
67479560

On Mon, 7 Feb 2022 05:19:44 +0000, Naz (LKKAuto) wrote

> Dear Mr Tan,

>

> The repair limit for this vehicle is \$20k. Kindly acknowledge if you can repair this vehicle within that limit.

>

> Thank you.

>

> Best Regards,

> **Naz** | Technical Investigator

> **LKK Auto Consultants**

> Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

> Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--