

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1SET	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 250.00	\$ 250.00
5	REVERSE CAMERA <i>Damaged</i>	1 SET	\$ 380.00	\$ 380.00
6	REAR FENDER INNER COWLING CLIPS <i>new</i>	2 SET	\$ 60.00	\$ 60.00
7	REAR FENDER INNER TRIM CLIPS <i>new</i>	2 SET	\$ 60.00	\$ 60.00
8	SPARE TYRE INSULATOR PAD <i>new</i>	1 SET	\$ 200.00	\$ 200.00
9	END PANEL INSULATOR SEAL <i>new</i>	2	\$ 80.00	\$ 80.00
Total Special Nett Items				\$ 1,140.00

690

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS		\$ 2,000.00
		<i>1000</i>
Spray Painting		Quotation
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 2,000.00
		<i>1000</i>
Others Cost (Accident Repair Related Expenses)		Quotation
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY		\$ 150.00
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS		\$ 350.00
TO REMOVE/ REFIT WIRING CHECKS ON TAILLAMPS		\$ 120.00
TO CONDUCT WATER LEAKAGE TEST		\$ 150.00
TO REMOVE/ REPLACE REAR SILENCER BOX		\$ 120.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING		\$ 150.00
TO REMOVE AND REPLACE BOOTLID MECHANISM		\$ 120.00
Total Others Cost		\$ 1,360.00
GRAND TOTAL		\$ 16,097.68

2320

Adrian Lij
w/s 26/01/22
06 Days

total: 8181.44

w/s: 6.5K

6.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: