




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS3/ASM22001063/Vvy3e2 Date: 16/03/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 5470C	Veh. Inspected	SFZ 8080H
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S2M03S9B	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	04/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053BK4107032320	Colour	WHITE
	Odometer	204583 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	TOURADOR	6 mm
	L/H Front Tyre	215/60 R16	TOURADOR	6 mm
	R/H Rear Tyre	215/60 R16	TOURADOR	6 mm
	L/H Rear Tyre	215/60 R16	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	18/01/2022	Inspect Date / Time	11/02/2022 (12:00 PM)
	Survey held at	AUTO BEST MOTOR SERVICES BLK 3006 UBI ROAD 1 #01-362 SINGAPORE 408700		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM22001063/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.