

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

ZOOMOOV PTE LTD
40 Jalan Pemimpin
#04-09 Tat Ann Building
Singapore 577185

Not Authorised
11 Rps @ 500dp
Running After Paint
7 days

Vehicle No : GBD 1691 D
Make/Model : Nissan NV200
Year : 2018

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear n/s tail-gate assy <i>1285</i>		\$1,496.60 ✓
1 pc	Rear n/s tail-gate inner trim board		\$287.10 X
2 pcs	Rear n/s tail-gate hinge		\$190.20 X
1 pc	Rear n/s tail-gate upper lock <i>215.50</i>	\$95.10	\$287.60 X
1 pc	Rear n/s tail-gate lower lock		\$268.20 X
1 pc	Rear n/s tail-gate outer handle		\$187.30 X
1 pc	Rear n/s tail-gate emblem "NV200"		\$55.10 ✓
1 pc	Rear n/s tail-gate emblem "LOGO"		\$65.20 ✓
1 pc	Rear n/s tail-lamp assy		\$282.10 X
1 pc	Rear boot rubber	<i>112.95 SN</i>	\$225.90 <i>50 Rps</i>
1 pc	Rear end panel		\$268.70 ✓
1 pc	Rear end panel inner garnish		\$125.60 ✓
1 pc	Rear bumper <i>624.80</i>		\$672.10 ✓
1 pc	Rear bumper sponge		\$137.10 ✓
2 pcs	Rear bumper side retainer		\$110.20 X
2 pcs	Rear bumper reflector	\$55.10	\$210.20 X
1 pc	Rear boot floor panel	\$105.10	\$1,347.10 ✓
			\$6,216.30
		Less 10 %	\$621.63
			\$5,594.67
<u>S Nett</u>			
2 pcs	Rear tail-gate glass sealant		\$70.00 <i>40 Rps</i>
1 pc	Rear reverse sensor	\$35.00	\$200.00 ✓
1 pc	Rear o/s tail-gate sticker "6 Pax"		\$15.00 ✓
1 pc	Rear n/s tail-gate sticker "70 kmph"		\$15.00 ✓
			\$300.00
	balance c/f		\$5,894.67

GBD 1691 D

Labour Charges

	balance b/f	\$5,894.67
Remove/renew the above parts including knocking, welding & cutting		\$1,600.00 <i>1200</i>
To putty and spray paint		\$1,400.00 <i>800</i>
Check & reconnect wiring.		\$30.00 <i>15</i>
To respray anti-rust proofing treatment		\$150.00 <i>90</i>
Remove/refit both rear tail-gate glass		\$100.00 <i>60</i>
Remove/refit both rear tail-gate mechanism to new door		\$120.00 <i>50</i>
	Total	<u>\$9,294.67</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: