

(199806235M)

Vehicle No. SLT8309K MADZA 3 SEDAN 1.5 AT EU6

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper center top bracket BR		24.00 ✓	
1	Tail lamp RH BR		534.00 ✓	
			-20%	
			558.00	
			-111.60	
			446.40 ✓	
	<u>SPECIAL NETT ITEMS</u>			
1	Rear bumper rivet		50.00 X nn	
	<u>LABOUR</u>			
		Total Parts	496.40	