

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

📄 ▾

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref: CS/CTI22001120/Rqf3	
3 ANSON ROAD #16-00			Date: 07/02/2022	
SPRINGLEAF TOWERSINGAPORE 079909			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		SND 2228K	Veh. Inspected SG 3036R	
Policy No.			Coverage (\$)	
Claim No.		SNM22D200789/C02	Excess (\$)	
Assign From		BILLY TAN	Assign Date 07/02/2022	
2. Vehicle Particulars & Condition				
Make & Model			c.c	
Engine No.		HIDDEN	Year of Reg.	
Chassis No.			Colour	
Odometer		-	Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date		01/02/2022	Inspection Date 08/02/2022	
Survey held at		310 Mandai Rd, Singapore 779404		
Repairer		TOWER TRANSIT SINGAPORE PTE. LTD.		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				