



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001129/Gqf3m4 Date: 25/07/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 6277M	Veh. Inspected	SLW 2597T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/22/2005	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	07/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI ELANTRA	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU628405	Colour	BEIGE
	Odometer	83470 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/02/2022	Inspection Date	08/02/2022
	Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	