

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 48992400W

*not Arthur
 Lm
 10/1/22
 1/5 \$3600
 4 days*

Vehicle Number: GBJ4104G

Vehicle Model : Nissan NV350 Panel Van 2.5 5AT 5DR EURO V

Manufacturing Year : 2014

Chassis : JN1MC2E26Z0001861

Nett item

S/N.	Item Description	Amount (\$)
1	Front Panel <i>R</i>	\$ 1,776.31 <i>X</i>
2	Corner Panel (LH) <i>PD 534.60</i>	\$ 743.63 <i>/</i>
3	Front Grille Assy <i>CNE 479.30</i>	\$ 733.06 <i>/</i>
4	Front Nissan Logo <i>NA</i>	\$ 109.89 <i>X</i>
5	Headlamp (LH) <i>320 441.40</i>	\$ 669.77 <i>/</i>
6	Front Bumper <i>DLS 571.90</i>	\$ 795.51 <i>/</i>
7	Front Bumper Side Retainer (LH) <i>CNE 185</i>	\$ 169.70 <i>/</i>
8	Foglamp Assy (LH) <i>CNE 355.20</i>	\$ 472.94 <i>/</i>
9	Towing Cover <i>NA</i>	\$ 33.38 <i>X</i>
10	Step Garnish (LH) <i>DLS</i>	\$ 144.66 <i>/</i>
11	Front Door (LH) <i>R</i>	\$ 1,490.32 <i>X</i>
12	Front Door Hinge (LH) x 2 pcs <i>NA</i>	\$ 239.25 <i>X</i>
13	Front Door Weatherstrip (LH) <i>NA</i>	\$ 164.14 <i>X</i>
14	Oil Cooler (LH) <i>D/Pun 716.20</i>	\$ 1,129.49 <i>/</i>
Total :		\$ 8,672.05
<i>10%</i> Less 30%		\$ 2,601.62
Amount :		\$ 6,070.44

S/N	Special Nett Item	Amount (\$)
1	Front Number Plate with Casing <i>NA</i>	\$ 60.00 <i>X</i>
2	Side Marking <i>for door 'Row' sticker new</i> <i>neg</i>	\$ 25.00 <i>/</i>
Amount :		\$ 85.00

Labour	Amount (\$)
To check front wiring system	\$ 80.00 <i>20</i>
To transfer LHF door components from old door to new door	\$ <i>NA</i> 100.00 <i>X</i>
To remove & install oil cooler	\$ 80.00 <i>30</i>
Labour to remove, cut, change & panel beating	\$ 1,200.00 <i>600</i>

To putty and respray affected areas	\$ 1,300.00
Labour Total :	\$ 2,760.00
Total (Parts & Labour)	\$ 8,915.44

780

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3412-96
102
P- 3071-66
S.N - 25
L - 1430
4526.66
213
3671