

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄	🖨	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD 10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Ref: CS/ICS22001136/Aqf3 Date: 07/02/2022 Code: ICS		
1. Policy Particulars :- OWN DAMAGE (RESURVEY INSPECTION)				
Insured Veh.	Veh. Inspected		SML 2396C	
Policy No.	MPC21P00120600	Coverage (\$)	0.00	
Claim No.	DMPC2200048H	Excess (\$)	3,750.00	
Assign From	MERIMEN (LIU CHUN CHEONG)	Assign Date	07/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2022	Inspection Date	08/02/2022	
Survey held at	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
THE MARKET VALUE IS S\$ (EST.AVERAGE)				