

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub, Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877  
 Attention : Motor Claim Department  
 Contact : 65073848 Fax No. : 65073849

**Estimate : TP22-014**

Date : 29.01.2022  
 Vehicle Num. : JPD6189  
 Make/Model : Toyota Vios-2015  
 Chassis/Eng# : PN153HYF005080153/1NZZ328810  
 Accident Date : 27.01.2022  
 Claim No. :  
 Reference :  
 Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		<b>LIST ITEMS :</b>		
1.	1 pc	Rear Boot Lid		890 987.10 / OT
2.	1 pc	Rear Boot Lid Toyota Logo		58.90 / Nee
3.	1 pc	Rear Boot Lid 'Vios' Emblem		64.20 / Arc
4.	1 pc	Rear Boot Lid 'G' Emblem		49.60 / Arc
5.	1 pc	Rear Boot Lid Chrome Trim Moulding		213 436.70 / OT
6.	1 pc	Rear No. Plate Lamp		83.60 / r19
7.	1 pc	Rear Boot Lid Mechanism Lock		220 438.80 / jam
8.	2 pcs	Rear Boot Hinge L/R	97.10	194.20 / r5vc
9.	2 pcs	Rear Lamp Assy L/R	423.10	846.20 / r5vc
10.	1 pc	Rear Boot Lid Weatherstrip		190 258.40 / cut
11.	1 pc	Rear Bumper Assy		638 731.50 / OT
12.	10 pcs	Rear Bumper Clips	5.79	30 57.90 / Nee
13.	2 pcs	Rear Bumper Side Holder L/R	254.90	509.80 / X5rc
14.	2 pcs	Rear Bumper Bracket L/R	97.60	195.20 / Nee
15.	1 pc	Rear End Panel		219 915.60 / OT
16.	1 pc	Rear End Panel Inner Top Garnish		180.70 / BT
17.	1 pc	Rear Floor Spare Tyre Panel		698.70 / Xr
18.	1 set	Reverse Sensor		380.70 / 20064
		List Total S\$ :		7,087.80
		25.00% Discount S\$ :		1,771.95
				5,315.85
		<b>SPECIAL NETT ITEMS :</b>		
1.	1 pc	Rear No. Plate		50.00 / 40 cra
		Special Nett Total S\$ :		50.00
		<b>LABOUR :</b>		
		To remove, rearrange electrical wirings, check lighting		120.00 / 40

CONTINUE / ...

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
Kaki Bukit Autohub. Singapore 417921  
Tel No. : 67461515 / 67471787 Fax No. : 67485015  
Website : www.successunited.com.sg  
Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited  
36 Robinson Road  
#16-01 City House  
Singapore 068877  
Attention : Motor Claim Department  
Contact : 65073848 Fax No. : 65073849

## Supplementary Estimate : TP22014S

Date : 10/02/2022  
Vehicle Num. : JRD6189  
Make/Model : Toyota Vios-2015  
Chassis/Eng# : PN153HYF005080155/1NZZ328810  
Accident Date : 24/01/2022  
Claim No. :  
Reference :  
Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	2 pcs	LIST ITEMS : Rear Bumper Reflector L/R	116.80	233.60 ✓ Cra
		List TotalSS :		233.60
		25.00% Discount SS :		58.40
				175.20

Total S\$ : 175.20  
=====

  
\_\_\_\_\_  
SUCCESS UNITED PTE LTD

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub. Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited  
 36 Robinson Road  
 # 16-01 City House  
 Singapore 068877

Attention : Motor Claim Department  
 Contact : 65073848 Fax No. : 65073849

## Estimate : TP22-014

Date : 29/01/2022  
 Vehicle Num. : JRD6189  
 Make/Model : Toyota Vios-2015  
 Chassis/Eng# : PN153HYF005080155/1NZZ328810  
 Accident Date : 27.01.2022  
 Claim No. :  
 Reference :  
 Policy No. : (22/11/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		To remove, reinstal upholstery, inner trim garnishes.	250.00	50
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	1,600.00	400X 800
		To putty and respray painting on affected area.	1,200.00	<del>400</del> 800
		Labour Total S\$ :	3,170.00	

*Theran @ LK Auto. loan  
 82235769  
 8/2/22 1200  
 LFS 7 days wp  
 6*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*5331.5  
 - 20%  
 = 4265.2  
 = 4250  
 F. 4300*

  
 SUCCESS UNITED PTE LTD

Total S\$ : 8,535.85  
 =====  
 8711.05