



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22001144/vf3e2 Date: 07/03/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 324B	Veh. Inspected	JRD 6189
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/01/22/7032	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	07/02/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS E	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	PN153HYF005080155	Colour	SILVER
Odometer	142104 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	5 mm
L/H Front Tyre	185/60 R15	MICHELIN	5 mm
R/H Rear Tyre	185/60 R15	MICHELIN	5 mm
L/H Rear Tyre	185/60 R15	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/01/2022	Inspection Date	08/02/2022
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	