



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDINGSINGAPORE 079120 ATTN: LOH CHEE HENG			Ref: CS3/AIG21007919/Rvf3n2-1 Date: 23/02/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMW 5742J	Veh. Inspected	SKR 1018T	
Policy No.	2070162742	Coverage (\$)	0.00	
Claim No.	3358646511SG	Excess (\$)	0.00	
Assign From	LOH CHEE HENG	Assign Date	08/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A6 2.0 TFSI MU	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ4G1EN049367	Colour	BLACK	
Odometer	89168 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35 ZR20	PIRELLI	6 mm	
L/H Front Tyre	255/35 ZR20	PIRELLI	6 mm	
R/H Rear Tyre	255/35 ZR20	PIRELLI	6 mm	
L/H Rear Tyre	255/35 ZR20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2021	Inspection Date	26/07/2021	
Survey held at	RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	