



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22001173/Kvf3e2	
			Date: 14/03/2022	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKQ 3950T
	Policy No.	DHOM110178172100	Coverage (\$)	0.00
	Claim No.	M11D14562202	Excess (\$)	500.00
	Assign From	JOSEPHINE WONG	Assign Date	08/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MR053REH104508531	Colour	METALLIC SILVER
	Odometer	66761 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	YOKOHAMA	8 mm
	L/H Front Tyre	205/55 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	14/02/2022
	Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$40,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	