



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref: CS/UIO22001173/Kvf3	
146 ROBINSON ROAD			Date: 08/02/2022	
#02-01 UOI BUILDINGSINGAPORE 068909			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected SKQ 3950T		
Policy No.		Coverage (\$) 0.00		
Claim No. M11D14562202		Excess (\$) 0.00		
Assign From JOSEPHINE WONG		Assign Date 08/02/2022		
2. Vehicle Particulars & Condition				
Make & Model		c.c 0		
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 26/01/2022		Inspection Date 14/02/2022		
Survey held at		K.KIM HIN AUTOMOTIVE PTE LTD		
		160 SIN MING DRIVE, #02-20		
		SIN MING AUTOCITY		
		SINGAPORE 575722		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				