

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	---

Attn: Gabriel Wee

Date: 10 Feb 2022

**Preliminary Advice**

Vehicle No	: SND4866E	Accident Date	: 28/01/2022
Make	: TOYOTA PRIUS	Policy No.	: D21MFL0000447
Assignment Date	: 08/02/2022	Excess	: S\$0.00
Date of Inspection	: 08/02/2022	Est. Duration of Repair	: 0
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	90,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 127,000.00

COE / PARF Rebate	:S\$ 67,162.00
Salvage Value	:S\$
Margin for Repair	:S\$ 59,838.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :