

Performance Motors

BMW Dealer



INDIA INTERNATIONAL INSURANCE
64 Cecil Street #04, #05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

Your ref: SLQ774T
Our ref: DS/2505316/SNC8808C

Without Prejudice

11 April 2022

ACCIDENT INVOLVING VEHICLES SNC8808C & SLQ774T ON 05/02/22

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair : \$ 9,012.18	Excess : \$ -
Loss of Use : \$ 480.00 (\$120.00*4 days)	GIA/LTA Search : \$ 7.45
Loss of Rental : \$ -	Others : \$ -
	Total : \$ 9,499.63

A copy of each of the following supporting documents is enclosed:

1. Copy of Tax Invoice & Receipts
2. GIA/LTA search slip
3. Original Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Evelyn Chan at 6319-0175 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Cresendo Lagman
Customer Service Manager, Body & Paint

Bernard Wan
Service Manager – Body & Paint

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road
Sime Darby Business Centre, 315 Alexandra Road
East Coast Centre, 280 Kampong Arang Road
Ubi Service Centre, By-appointments only

Tel: 1800-2255-269
Co Reg No. 197401559W

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road
Sime Darby Performance
Singapore 159941
Tel. 63190100 (Sale)
63190111 (After)
Fax. 64747770

280, Kampong Arang
East Coast Centre
Singapore 438180
Tel. 63190888 (Aft)
Fax. 63449773

315, Alexandra Road
Sime Darby Business
Singapore 159944
Tel. 63190528
63190533/530
Fax. 64796601
64796624



SERVICE TAX INVOICE

Repair Order No. : B1 1637087

Date IN : 25/02/2022

Motor Claim Advisor: Chua Kee Sin

Page No. : 1 of 2

Invoice Number : 2505316 / WSB

Invoice Date : 05/04/2022

Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

- CUSTOMER INFORMATION -

Mr Tan Tze Woon (Chen ZhiWen)
21 Tampines Street 34
#07-04

Singapore 529232

- INVOICE TO - 219

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SNC8808C

CHASSIS NO.
WBAJA12070WW34954

REGN. DATE
26/06/2019

MODEL
520I

MILEAGE
76322

- - - - L A B O U R 1 - - - -

To replace rear bumper and attachments, bootlid including
knock out dented area caused by the accident.

NETT
1,700.00

To respray rear bumper and bootlid.

1,972.00

To carry out body cavity preservation.
(Per panel).

112.00

To remove old PDC assembly and reconnect to new bumper
including conduct check for proper function.

168.00

To transfer lock mechanism from old to new bootlid
including conduct check on new bootlid central locking system
for proper function.

504.00

To check electrical wiring system and lighting at the
rear section for proper function.

168.00

Sundries.

150.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 05.02.2022. 3RD PARTY CAR : SLQ774T.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK
CONSULTANT ON 25.02.2022 AT 1520HRS. AUTHORISED BY MR
BHUVANESWARI FROM INDIA INT'L INSURANCE VIA EMAIL ON
15.02.2022.

PROPOSE LOSS OF USE = \$120X4. THE AMOUNT IS SUBJECTED
TO

0.00

INSURANCE COMPANY CONFIRMATION.

LTA SEARCH FEE = \$7.45.

0.00

Total Labour 1: **4,774.00**

- - - - P A R T S - - - -

TAILGATE ALUMINIUM

Qty Retail
Price

1

1,818.60

1,818.60

REAR BUMPER PANEL PRIMED (PDC/PMA)

1

1,603.00

1,603.00

GROMMET

2

0.80

1.60

EXPANDING RIVET D=8MM

10

1.10

11.00

LETTERING 520I

1

65.60

65.60

REAR BUMPER BOTTOM REINFORCEMENT

1

75.95

75.95

PLAQUE 74MM

1

72.85

72.85

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559N GST Reg. No M2-00200

303, Alexandra Road
Sime Darby Performance
Singapore 159941
Tel. 63190100 (Sale)
63190111 (After)
Fax. 64747770

280, Kampong Arang
East Coast Centre
Singapore 438180
Tel. 63190888 (Aft)
Fax. 63449773

315, Alexandra Road
Sime Darby Business
Singapore 159944
Tel. 63190528 {
63190533/530 {
Fax. 64796601 {
64796624 {

**SERVICE TAX INVOICE**

Repair Order No. : B1 1637087

Date IN : 25/02/2022

Motor Claim Advisor: Chua Kee Sin

Page No. : 2 of 2

Invoice Number : 2505316 / WSB

Invoice Date : 05/04/2022

Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

Total Parts : 3,648.60

Labour Charges : 4,624.00
Parts Charges : 3,648.60
Lubricant/Misc : 150.00

Total Labour & Parts Charges : S\$ 8,422.60
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 8,422.60
GST @ 7% : S\$ 589.58
Invoice Total Amount Include GST : S\$ 9,012.18

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 9,012.18

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 07 Feb 2022 / 16:59:33

Receipt Date/Time : 07 Feb 2022 / 16:59:33

Tax Invoice/Receipt

Receipt No. : ITNET-00000-220207-002897

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLQ774T				
As at 05 Feb 2022/16:45:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SLQ774T			
	Enquiry Fee	7.00	0.49	7.49
	20220207165818914144			
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	542125XXXXXX4416	eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SNC8808C & SLG 774T ON 5/2/2022.


I, Tan Tze Woon owner of Vehicle Registration No. SNC8808C hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.


I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.


Signed by:


Name: Tan Tze Woon 7/2/22
NRIC No.: S90141268 (Date)

In the presence of:

Name: _____ (Date)
NRIC No.: _____




7/2/2022
@ 1328 hrs