



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel 67481000 Fax 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL: 67143369 Contact No	Cust No/Name /Cycle & Carriage Fulco Motor De Reg No/Reg Date GBI 1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7EFYH2RMJ542597 Engine No 10Q4DR0030181 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	31/01/2022/ 08:49	00	303 / Renemer	25421

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M C9800479780 SPRING SHOCK-ABSORBE	1.00	106.00	0.00	106.00
M C1647857180 LHF FRONT KNUCKLE ST	1.00	715.00	0.00	715.00
M C9815014680 LHF LWR ARM WISHBONE	1.00	489.00	0.00	489.00
M C9831088880 LHF BALL JOINT SUSPE	1.00	53.00	0.00	53.00
M C9833984280 * FRONT ANTI-ROLL BAR	1.00	508.00	0.00	508.00
M C9831547080 * LHF ANTI-ROLL BAR LI	1.00	78.00	0.00	78.00
M C1675954280 * STEERING RACK ASSY	1.00	2422.00	0.00	2422.00
M C9677071880 FRONT SUBFRAME CROSS	1.00	1122.00	0.00	1122.00
M C163627582D OTR DASHBOARD INST C	1.00	318.00	0.00	318.00
M C163627592D LH OTR DASHBOARD INS	1.00	109.00	0.00	109.00
M C981845422D * CTR OTR MLDG PANEL F	1.00	133.00	0.00	133.00
M C982534232D * OTR UPR CTR MLDG PAN	1.00	153.00	0.00	153.00
M C168419002D DASHBOARD	1.00	3686.00	0.00	3686.00
M C981655332D LH SIDE COVER-MTG	1.00	62.00	0.00	62.00
M C981943822D LH CTR COVER CONSOLE	1.00	16.00	0.00	16.00
M C9821348980 LHF AIR DUCT DASHBOA	1.00	95.00	0.00	95.00
M C981838072D INR GLOVE BOX FASCIA	1.00	229.00	0.00	229.00
M C982538812D MLDG GLOVE BOX	1.00	140.00	0.00	140.00
M C98253899VH UPR GLOVE BOX FASCIA	1.00	449.00	0.00	449.00

Z NOTES

ACCIDENT ON 17/01/2022 ALONG UPPER THOMSON ROAD

OWNER CLAIMING OWN POLICY

EXCESS AND AUTHORIZATION WILL BE ADVISE BY THE INSURANCE COMPANY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Thuan@Lthauto.com
92235464

excess TBC

PIP

12 days

Re-survey by paint.

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

Parts	21,263.00
Labour	0.00
Standard Menu	0.00
Specialist Job	15,520.00
Others(Lub,etc)	0.00
Sundry	192.00
Total(w/o GST)	36,975.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408050 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068907 TEL: 67143369 Contact No	Cust No/Name /Cycle & Carriage Fulco Motor De Reg No/Reg Date GBL1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7FFYH/RMJ542597 Engine No 10Q4UR0030181 Make/Model CITICV/K9 BERLINGO L2 1.5 BLUEHD 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	31/01/2022/ 08:49	OD	303 / Renemer	25421
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M C9830100580	* IR BUMPER INR FRAME	1.00	285.00	0.00	285.00
M C9821847480	LH FRONT BUMPER BRAC	1.00	105.00	0.00	105.00
M C1632655880	SET BUMPER LAT REINF	1.00	147.00	0.00	147.00
M C9830512660	* FRONT PANEL CROSSMEM	1.00	201.00	0.00	201.00
M C9830502280	* LH BRACKET CROSSMEMB	1.00	105.00	0.00	105.00
M C9827055880	LHF UNIT FACING SUPP	1.00	201.00	0.00	201.00
M C9817397480	LH COOL AIR ANTI-REC	1.00	106.00	0.00	106.00
M C9816462780	LHF FENDER WING	1.00	434.00	0.00	434.00
M C9817764580	* LHF FENDER SUPPORT A	1.00	189.00	0.00	189.00
M C981769144T	LH DRIP MOULDING	1.00	87.00	0.00	87.00
M C632563	LH SIDE FLASH-UNIT	1.00	27.00	0.00	27.00
M C9821666680	LHF FENDER REAR SEAD	1.00	217.00	0.00	217.00
M C9817398580	LH WHEEL HOUSING MUD	1.00	170.00	0.00	170.00
M C9816437980	LH PASS COMP FR STRG	1.00	185.00	0.00	185.00
M C9820423380	LH FRONT DOOR	1.00	1462.00	0.00	1462.00
M C981769634T	LH DOOR PROTECTOR	1.00	336.00	0.00	336.00
M C9820661360	LH FR DOOR W/STRIP O	1.00	79.00	0.00	79.00
M C9817683280	LH RR DOOR W/STRIP	1.00	93.00	0.00	93.00
M C9825723980	LH FR INR DOOR W/STR	1.00	124.00	0.00	124.00
M C1606475180	LH UPR HINGE DOOR	1.00	124.00	0.00	124.00
M C9035AZ	LH LWR HINGE DOOR	1.00	124.00	0.00	124.00
M C9816977280	DOOR ARRESTER	1.00	111.00	0.00	111.00
M C981679122D	LH DOOR TRIM LINING	1.00	495.00	0.00	495.00
M C981679282D	LH DOOR TRIM CHEATER	1.00	39.00	0.00	39.00
M C9819576080	LH INR SEALING DOOR	1.00	50.00	0.00	50.00
M C9827671580	LH SIDE PASSENGER CO	1.00	2233.00	0.00	2233.00
M C9817300960	WINDOW WASHER RESERV	1.00	232.00	0.00	232.00
M C9816645860	WASHER PIPE SCREENWA	1.00	57.00	0.00	57.00
M C9804681780	FUSE BOX SUPPORT	1.00	58.00	0.00	58.00
M C98153116VT	STEEL WHEEL	1.00	195.00	0.00	195.00
M C98083420XT	WHEEL CAP	1.00	56.00	0.00	56.00
M C9833306080	LHF SHOCK ABSORBER	1.00	225.00	0.00	225.00
M C9678782580	ROD PROTECTOR SHOCK	1.00	13.00	0.00	13.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857




ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL: 67143369 Contact No	Cust No/Name	/Cycle & Carriage.Fulco Motor De
	Reg No/Reg Date	GBL1784C / 30/03/2021
	Date In/Mileage	17/01/2022/ 6319
	Chassis No	VR7EFYH2RMJ542597
	Engine No	10Q4DR0030181
	Make/Model	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13
	Colour/Trim	WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000051	Credit	26/05/2022/ 09:39	0D	303 / Renemer	25421			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	C1610817780	LH STEERING ROD BALL	/	GBT	1.00	195.00	0.00	195.00
X	C9677914480	LHF DRIVE SHAFT	/	CRA	1.00	650.00	0.00	650.00
M	C9816824080	RH HEADLIGHT ASSEMBL	/	BR	1.00	620.00	0.00	620.00
M	C98029781XT	LH DOOR HANDLE	/	MC	1.00	67.00	0.00	67.00
M	C9822171580	LH DOOR ADHESIVE TAP	/	MC	1.00	10.00	0.00	10.00
M	C9818018380	LH W/STRIP DOOR ENTR	/	MC	1.00	207.00	0.00	207.00
M	C9675747980	RADIATOR ASSY	/	BR	1.00	545.00	0.00	545.00
M	C9830335880	LH WINDOW LIFTER ELE	/	CRA	1.00	492.00	0.00	492.00
Z	NOTES							
SUPPLEMENTARY ITEMS								

SUPPLEMENTARY ITEMS

Estimate


 27/5/22

Confirm & accepted by

Parts	2,786.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	2,786.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.