



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001220/Kvf3e2	
			Date: 25/02/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 3769B		Veh. Inspected	SLD 3901S
Policy No.			Coverage (\$)	0.00
Claim No.	D22000353MFCV		Excess (\$)	0.00
Assign From	AINI BINTE		Assign Date	09/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ODYSSEY (A)		c.c	2356
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	RC11110768		Colour	METALLIC BLACK
Odometer	75077 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		215/55 R17	YOKOHAMA	7 mm
L/H Front Tyre		215/55 R17	YOKOHAMA	7 mm
R/H Rear Tyre		215/55 R17	YOKOHAMA	7 mm
L/H Rear Tyre		215/55 R17	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/01/2022		Inspection Date	09/02/2022
Survey held at	CONVINCE AUTO PTE LTD 176 SIN MING DRIVE #04-04 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	