

Our Job Ref No : 305504236

Date : 14/02/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SHC 533T CCPL

08/02/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- EM778L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$143.09
 - (b) Labour Charges \$1,311.00
 - Total for Part-By-Part Repair Cost** \$1,454.09
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : _____

Name : Thevan

Date : 16/3/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.02.2022
Time: 10:48:36
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305504236
REGN NO : SHC 533T
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 01.04.2019
DATE/TIME IN : 08.02.2022 08:05
ACCIDENT DATE : 08.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	86.50	25.00	64.87
0002 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0003 04-01-0302-2971-G	SUPPORT FRONT BUMPER SIDE	1	82.30	25.00	61.72

SUB-TOTAL : 143.09

JOB NATURE

0000 L	MERIMEN FEE	11.00
0001 PB	PANEL BEATING SHC0533T	700.00
0002 SP	SPRAYPAINT CHARGE	500.00
0003 17-01	CHECK ALL LIGHTING	20.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0005 23-01	TOWING FEE	60.00

SUB-TOTAL : 1,311.00

2/8/22, 1:06 PM

Repairer Estimates

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2022)
Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC533T/08/02/2022 13:06
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER HYBRID EMBLEM RH			
2	1		*FRONT BUMPER FOG LAMP	25.00	0.00	*86.50 FL /NIC
3	1		*HEADLAMP RH	25.00	0.00	*920.00 FL /XSC
4	1		*FRONT BUMPER COVER	25.00	0.00	*2,637.60 FL /XSC
5	1		*FRONT BUMPER CLIPS	25.00	0.00	*499.90 FL /Xr
6	1		*FRONT BUMPER SIDE BRACKET RH	25.00	0.00	*22.00 FL /NIC
				25.00	0.00	*82.30 FL /NIC
Sub Total (S\$)						4,248.30
- List Item Discount on L Items (S\$)						1,062.08
Total Parts (S\$)						3,186.22

ComfortDelGro Engineering Pte Ltd/SHC533T/08/02/2022 13:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS