



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

14/2/2022

### Survey Details:

Date of loss	24-Jan-22
Date of appointment	9-Feb-22
Date of survey	9-Feb-22
Location of survey	A T PERFORMANCE

### Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	GBC 3825C
Make and Model	TOYOTA HIACE MANUAL
Date of registration	24/2/2012
Excess	-
Market Value	\$ 4,000.00
Parf Rebate	\$ 149.00
Nett Loss	\$ 3,851.00

### Repair details:

Initial Estimate	\$ -
------------------	------

### Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
<b>Total</b>	\$ -
<b>Lump Sum(if applicable)</b>	

<b>Number of days for repair</b>	<b><u>5</u></b>
----------------------------------	-----------------



**Remarks:**

*The estimate repair cost of the damaged vehicle is in the region of \$4,000.00 - \$5,000.00.*

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>	<b>#VALUE!</b>	