

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CS/CTI22001236/Uty3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date:	09/02/2022	
			Code	СТІ	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 7136R	Veh. Inspected	FBP 9753T	
	Policy No.	DMCVSNW00039892104	Coverage (\$)	0.00	
	Claim No.	SNM22D200862/C02/TANKW	Excess (\$)	0.00	
	Assign From	TAN KIAN WEI BILLY	Assign Date	09/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
5.		General Information			
	Accident Date	07/02/2022	Inspection Date	10/02/2022	
	Survey held at	NEW UNION COMPANY			
		9004 TAMPINES ST 93 #01-06 SINGAPORE 528838			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				