



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 5071B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SET FRONT WINDSCREEN RUBBER COME WITH GLASS	NOT NECESSARY	1,642.90	-
1	FRONT PANEL	DENTED	1,690.00	985.00
1	FRONT GRILLE	CRACKED	720.00	654.00
1	FRONT GRILLE LOGO	NECESSARY	128.00	71.00
1	FRONT WIPER LINK	NOT NECESSARY	487.90	-
	LESS 10% DISCOUNT		-	-171.00
			4,668.80	1,539.00
<b>SPECIAL NETT ITEMS</b>				
1	FRONT HINO STICKER (SN)	NECESSARY	78.00	78.00
1	FRONT 300 STICKER (SN)	NECESSARY	58.00	58.00
1	FRONT BUDDHA STICKER (SN)	NECESSARY	480.00	180.00
1	ERP IU BRACKET (SN)	NOT NECESSARY	35.00	-
			651.00	316.00
<b>LABOUR</b>				
	LABOUR FOR KNOCKING FLOOR PANEL ,WELDING ,CUTTING ,REPAIRING AND REPLACEMENT OF PARTS.		1,000.00	500.00
	TO SPRAY PAINT ON THE DAMAGE PARTS.		1,000.00	400.00
	TO DISMNATLE AND REFIT DASHBOARD .		480.00	220.00
	TO DISMANTLE AND REFIT AIRCON SYSTEM AND REFILL GAS.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND RENEW FRONT WINDSCREEN RUBBER .		200.00	120.00
	TO CHECK WIRING.		80.00	30.00
	TO APPLY RUST-PROOFING.		200.00	50.00
			3,340.00	1,320.00
<b>GRAND TOTAL</b>			<b>8,659.80</b>	<b>3,175.00</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,500.00</b>
---	--	--	-----------------

Report Ref No. CS/GAI22001242/Aqf3q2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**