

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000 / Email: info@carsmith.biz

VEHICLE NO: SLS8731D

MAKE & MODEL: HYUNDAI/ELANTRA

DOA: '23 April 2021

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$ 669.00	/cut
FRONT BUMPER RETAINER LH	1	\$ 56.00	X svc svc
FRONT BUMPER RETAINER RH	1	\$ 56.00	/NCC
FRONT BUMPER SPONGE	1	\$ 134.00	Xsvc
FRONT BUMPER REINFORCMENT	1	\$ 386.00	Xsvc
FRONT BUMPER FOG LAMP LH	1	\$ 298.00	Xsvc
FRONT BUMPER FOG LAMP COVER LH	1	\$ 134.00	Xsvc
FRONT HEADLAMP RH	1	\$ 1,589.00	/scr

474.4
1198.8

\$ 3,322.00
LESS 20% \$ 664.40
SUB TOTAL \$ 2,657.60

1929.2
1383.36

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER CLIP	1 SET	\$ 40.00	2D ncc

SUB TOTAL \$ 40.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK FRONT WIRING AND LIGHTNING SYSTEM	1	\$ 100.00	30
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 600.00	200
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	200
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	30

SUB TOTAL \$ 1,300.00

GRAND TOTAL \$ 3,997.60

1863.36
1490
=1500

thuan
82235769
10/2/22
relays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: