

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0082/2022/JT
DATE : 7-Feb-22
WIP : 10411

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIEW MUN KIONG
ADDRESS : 50 AMBER ROAD
#12-01
SINGAPORE 439888
TELEPHONE : HP +65 87818438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210074983
VEHICLE NO : **SMQ 8218 T**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 28/7/2021
ENGINE NO : CZD C41672
CHASSIS NO : WAUZZZF30M1128013
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Feb-22
PLACE OF ACCIDENT : 238 THOMSON ROAD CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 8218 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR COVERS AND BOTH FRONT WHEEL ARCH TRIMS.	\$	6,000.00	
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 10,432.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER - LH	1	\$ 1,423.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 433.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 66.00	
4	FRONT BUMPER CLOSING ELEMENT END PLATE	1	\$ 212.00	
5	FRONT BUMPER SPOILER	1	\$ 850.00	
6	FRONT BUMPER BRACKET	1	\$ 24.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	
8	FRONT BUMPER TRIM - LH	1	\$ 182.00	
9	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 29.00	
10	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	
11	FRONT BUMPER TOP COVER	1	\$ 137.00	
12	CAUTION STICKER	1	\$ 16.00	
13	AIR COND STICKER	1	\$ 9.00	
14	FRONT FENDER - LH	1	\$ 1,445.00	
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
16	FRONT FENDER BRACE - LH	1	\$ 98.00	
17	FRONT FENDER BRACKET - LH	1	\$ 39.00	
18	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	
19	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	
20	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
SUB TOTAL SPARE PARTS		:	\$ 5,645.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 18.00	
22	HEADLIGHT MOUNTING - LH	1	\$ 132.00	
23	HEADLIGHT - LH	1	\$ 5,952.00	
24	LIFT CYLINDER - LH	1	\$ 231.00	
25	LIFT CYLINDER HOSE - LH	1	\$ 92.00	
26	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,132.00	
27	FRONT DOOR COVER -- LH	1	\$ 390.00	
28	REAR DOOR COVER - LH	1	\$ 368.00	
29	ALUMINIUM RIM	1	\$ 1,414.00	
30	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 15,774.00	
TOTAL LABOUR CHARGES			\$ 10,432.00	
GRAND TOTAL			\$ 26,206.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT