

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0082/2022/JT
DATE : 07-Feb-22
WIP : 10411

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

5 days - ok - Jy - 23 Apr 22

OWNER'S NAME : MR LIEW MUN KIONG
ADDRESS : 50 AMBER ROAD
#12-01
SINGAPORE 439888
TELEPHONE : HP +65 87818438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210074983
VEHICLE NO : **SMQ 8218 T**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 28/07/2021
ENGINE NO : CZD C41672
CHASSIS NO : WAUZZZF30M1128013
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 04-Feb-22
PLACE OF ACCIDENT : 238 THOMSON ROAD CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 8218 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,500.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, TWO DOOR COVERS AND BOTH FRONT WHEEL ARCH TRIMS.	\$	6,000.00	\$	2,450.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00		
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 10,432.00	\$	5,152.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER - LH	1	\$ 1,423.00	\$ 1,138.40
2	FRONT BUMPER FIXING PARTS	1	\$ 433.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 66.00	
4	FRONT BUMPER CLOSING ELEMENT END PLATE	1	\$ 212.00	
5	FRONT BUMPER SPOILER	1	\$ 850.00	\$ 679.60
6	FRONT BUMPER BRACKET	1	\$ 24.00	\$ 18.56
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	
8	FRONT BUMPER TRIM - LH	1	\$ 182.00	
9	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 29.00	\$ 22.72
10	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	
11	FRONT BUMPER TOP COVER	1	\$ 137.00	
12	CAUTION STICKER	1	\$ 16.00	
13	AIR COND STICKER	1	\$ 9.00	
14	FRONT FENDER - LH	1	\$ 1,445.00	\$ 1,156.00
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
16	FRONT FENDER BRACE - LH	1	\$ 98.00	\$ 77.68
17	FRONT FENDER BRACKET - LH	1	\$ 39.00	\$ 30.48
18	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	
19	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	
20	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
SUB TOTAL SPARE PARTS		:	\$ 5,645.00	\$ 3,123.44

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 3,123.44
21	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 18.00	
22	HEADLIGHT MOUNTING - LH	1	\$ 132.00	
23	HEADLIGHT - LH	1	\$ 5,952.00	\$ 4,761.60
24	LIFT CYLINDER - LH	1	\$ 231.00	
25	LIFT CYLINDER HOSE - LH	1	\$ 92.00	
26	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,132.00	\$ 904.80
27	FRONT DOOR COVER -- LH	1	\$ 390.00	
28	REAR DOOR COVER - LH	1	\$ 368.00	
29	ALUMINIUM RIM	1	\$ 1,414.00	
30	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 15,774.00	\$ 8,789.84
TOTAL LABOUR CHARGES			\$ 10,432.00	\$ 5,152.00
GRAND TOTAL			\$ 26,206.00	\$ 13,941.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-30/03/22