



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8718R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER WITH REINFORCEMENT BAR	CUT	880.00	880.00
1	SIDE MIRROR MOUNTING PANEL COVER - RH	NOT NECESSARY	170.00	-
1	FRONT CORNER COVER - RIGHT	DENTED	380.00	380.00
1	FRONT DOOR RIGHT	NOT NECESSARY	1,880.00	-
2	FRONT DOOR HINGE - RIGHT @\$70.00	NOT NECESSARY	140.00	-
1	HEADLAMP - RIGHT	NOT NECESSARY	500.00	-
1	SIDE MIRROR - RIGHT	BROKEN	250.00	250.00
1	FRONT WINDSCREEN	BROKEN	400.00	400.00
	LESS 30% DISCOUNT		-1,380.00	-573.00
			3,220.00	1,337.00
1	SET FRONT WINDSCREEN MOULDING (SN)	NECESSARY	400.00	180.00
2	WINDSCREEN SEALANT @\$50.00 (SN)	NECESSARY	100.00	40.00
	LESS 30% DISCOUNT		-150.00	-
			350.00	220.00
<u>LABOUR</u>				
	MISCELLANEOUS - BOLTS, NUTS, SCREWS, CLIPS, ETC (SET).		142.50	30.00
	REMOVE & RENEW DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS.		1,000.00	300.00
	RESPRAY AFFECTED AREAS.		1,200.00	200.00
	TO APPLY CAVITY WAX COATING ON AFFECTED AREAS.		150.00	30.00
	LABOUR TO CHANGE WINDSCREEN.		150.00	120.00
	HEADLAMP LEVEL ADJUSTMENT.		30.00	30.00
			2,672.50	710.00
GRAND TOTAL			6,242.50	2,267.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CS/FCI22001263/Evf3e2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.