Hsiao Tong (LKKAuto)

From: EDWIN KANG WEE HUAT <KANG_Wee_Huat_Edwin@defence.gov.sg>

Sent: Monday, 9 May 2022 1:01 PM

To: Hsiao Tong (LKKAuto)

Cc: HO AIK SENG, DENNIS; RISHABH RADHAKRISHNAN

Subject: Re: [Seek Mandate] - Your Ref: CY 22/MID52157/060122/0003 // LKK Ref:

CC2/MIDA22001277/Ep

Message Classification: Official Open

Approved. Thanks.

Get Outlook for Android

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Monday, May 9, 2022 11:35:51 AM

To: EDWIN KANG WEE HUAT <KANG_Wee_Huat_Edwin@defence.gov.sg>

Cc: HO AIK SENG, DENNIS <HO_Aik_Seng_Dennis@defence.gov.sg>; RISHABH RADHAKRISHNAN

<Rishabh Radhakrishnan@defence.gov.sg>

Subject: [Seek Mandate] - Your Ref: CY 22/MID52157/060122/0003 // LKK Ref: CC2/MIDA22001277/Ep

Your ref: CY 22/MID52157/060122/0003

LKK ref: CC2/MIDA22001277/Epq2

Dear Maj Edwin,

ACCIDENT INVOLVING MID51257 AND GBJ8874R ON 06/01/2022

We refer to the above matter.

Please be informed that our SAF driver collided onto civilian parked vehicle. We are of the view our SAF driver is at fault.

We would like to seek your approval to negotiate and settle with civilian repairer.

The summary is as follows: -

	Claimed Amount	Mandate Amount
1. Cost of Repair (w/GST)	\$ 7,838.82	\$ 4,251.91 (\$3,973.75 + 7%GST)
2. Loss of Use (4days x \$180.00)	\$ 720.00	\$ 480.00 (4days x \$120.00)
Total	\$ 8,558.82	\$ 4,731.91

Enclosed herewith: -

- Survey Report & Photos GBJ8874R.
- LOD GBJ8874R
- SAF Report & Photos MID51257

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Wednesday, 16 February 2022 2:19 PM

To: EDWIN KANG WEE HUAT <KANG_Wee_Huat_Edwin@defence.gov.sg>

Cc: HO AIK SENG, DENNIS < HO_Aik_Seng_Dennis@defence.gov.sg>

Subject: Your Ref: CY 22/MID52157/060122/0003 // LKK Ref: CC2/MIDA22001277/Ep

Your Ref: CY 22/MID52157/060122/0003

LKK Ref: CC2/MIDA22001277/Ep

Dear Sirs,

We have conducted inspection for GBJ8874R.

Please refer to the attached appraisal of damaged vehicle before repair and photos for your perusal.

Our further advice will follow in due course.

Thank you.

Best Regards, **Hsiao Tong, Chew** | Case Handler **LKK Auto Consultants Pte Ltd**Phone: 6742 3197 | email: chewht@lkkauto.com | fax: -

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<< Message from Defence Mail Administrator>>: Please be informed that the direct URL linking and clicking has been disabled. Copy and paste the URL to the browser to access the website. Thank you.

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."