



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA22001279/Vvf3e2 Date: 13/05/2022  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YN 9305S	Veh. Inspected	SLX 4330C
Policy No.	BVFCB0013842100	Coverage (\$)	0.00
Claim No.	NSV2200019/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	10/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI OS KONA	c.c	998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHK3811LJU089817	Colour	GREY
Odometer	123200 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/02/2022	Inspection Date	14/02/2022
Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	