



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22001291/Uvy3e2 Date: 18/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4682A	Veh. Inspected	XE 1119A	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S2M03T05	Excess (\$)	0.00	
Assign From	TEO KITTY	Assign Date	10/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FV51 (M)	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	FV51SJA10221	Colour	WHITE	
Odometer	334236 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	CENTARA	6 mm	
L/H Front Tyre	295/80 R22.5	CENTARA	6 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	CENTARA	6/6/6/6 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	CENTARA	6/6/6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2022	Inspection Date	14/02/2022	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	