

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	Ref:		CS3/LPC22001299/Rvf3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	23/02/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBD 9660R	Veh. Inspected	ł	SLP 1470T
	Policy No.	Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025425	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		11/02/2022
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA3 4-DOOR SEDAN 1.5L	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JM6BM42A8G0347051	Colour		BLACK
	Odometer	118346 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	тоуо		6 mm
	L/H Front Tyre	205/60 R16	тоуо		6 mm
	R/H Rear Tyre	205/60 R16	тоуо		6 mm
	L/H Rear Tyre	205/60 R16	тоуо		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	28/01/2022	Inspect Date /	Time	11/02/2022 ( 02:58 PM )
	Survey held at	7 Sin Ming Ind. Estate Sector C #01-82			
	Repairer	CAR LABORATORIES PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22001299/Rvf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser