

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ▼	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS/CTI22001306/Bqf3		
3 ANSON ROAD #16-00		Date: 11/02/2022		
SPRINGLEAF TOWERS SINGAPORE 079909		Code: CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 2990L	Veh. Inspected	SMS 2607H	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM22D200982/C02/	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	11/02/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2022	Inspection Date	14/02/2022	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				