



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001316/Rvf3e2	
			Date: 11/04/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 712Z	Veh. Inspected	SMW 268U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/22/2011	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	11/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SERENA 1.2L HIGHWAY STAR	c.c	1198
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JN1EBAC27Z0000612	Colour	BLACK
	Odometer	13564 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	DUNLOP	6 mm
	L/H Front Tyre	195/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	195/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	195/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/02/2022	Inspection Date	11/02/2022
	Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	