

ASS. REC. BY: P. J. S. S.REF: CS/SMR 22001316/RVf3

6772

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMW 2684at Workshop m/s Auto Insureof 6, MARILYN LNInsured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 139K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMW 2684Yr Regn: 2021 JANType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISSAN SERENA 1.2 H.S c.c. 1198Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: 13564

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1EBAC2720000612Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/60R16R: 22BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 07/02/22

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 4/02/22

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 80K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Photos

Others

Report Format: _____

Lump Sum / L.B.I. (\$ _____)



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SMW268U (SIEW)**

Your Ref: **SHB712Z**

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Date: **11-Feb-22**

ATTENTION: MOTOR CLAIMS DEPT

Email : motor_claims@first-insurance.com.sg

First Capital Insurance Limited

6 Raffles Quay #21-00
Singapore 048580

Assessed Vehicle No : **SMW268U**
Car Make and Model : **NISSAN SERENA 1.2L HIGHWAY STAR PREMIUM E-POWER**
Date of Accident : **7-Feb-22**
Date of Assessment : **11-Feb-22**

We have carried out a physical assessment of SMW268U at our workshop Auto Insure Pte Ltd sustained damages to the FRONT RH portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**
Adjusted Amount : **\$ 5,956.05**
Est. Repair Days : **4**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SMW268U

Your Ref: SHB712Z

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	HEADLAMP RH <i>X</i>		\$ 1,978.00
2	1	FRONT BUMPER <i>See ✓</i>		\$ 1,260.00
3	1	FRONT BUMPER FOG LAMP COVER RH <i>See ✓</i>		\$ 120.00
4	1	FRONT BUMPER SIDE RETAINER RH <i>X</i>		\$ 71.00
5	1	FRONT FENDER RH <i>repair</i>		\$ 1,167.00
			SUB TOTAL	\$ 4,596.00
			LESS 10%	\$ 459.60
			TOTAL AMOUNT	\$ 4,136.40

Our Ref: SMW268U

Your Ref: SHB712Z

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS <i>re ✓</i>		\$ 50.00 <i>30</i>
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 4,186.40

Our Ref: **SMW268U**

Your Ref: **SHB712Z**

S/NO	DESCRIPTION	EST. BY WORKSHOP
	LABOUR & PAINTWORK	
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 300 500.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ X 100.00
3	TO REMOVE & REFIT FRONT BUMPER PARKING SENSORS	\$ 60 80.00
5	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 400 500.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ X 40.00
7	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ X 50.00
8	TO VACUUM, WAXING & CLEAN	\$ X 60.00
9	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ X 50.00
TOTAL BEFORE GST		\$ 5,566.40
GST 7%		\$ 389.65
TOTAL (PARTS & LABOUR):		\$ 5,956.05

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 5,956.05 for part by part with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

3 days

48

11/02/22 @ 1555

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/02/2022 15:51 (SGT)
Date of Accident 07/02/2022 08:47 (SGT)
Exact Location of Accident Henderson Rd, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW268U

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner WONG PAK LAP BENNETT
NRIC No SXXXX677Z
Email Address BENNETT.WONG@HOTMAIL.COM
Mobile Phone No (Phone) +65-94364901
Alternative Phone No +65-94364901

VEHICLE PARTICULARS

Manufacturer Nissan
Model Serena
Variant 1.2L HIGHWAY STAR PREMIUM E-POWER
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1198

INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MT/00996165
Cover Note Number -

DRIVER

Date of Birth	09/11/1980
Occupation	Indoor
Date of Driving Pass	07/05/2010
Driving experience	11 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94364901
Alt. Phone Number	+65-94364901
Email Address	BENNETT.WONG@HOTMAIL.COM
Address	BLK 112A DEPOT ROAD #25-119
Address complement	-
Postcode	S101112
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	NA
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT


REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20220207/7019

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20220207/7019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/02/2022 11:57		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: WONG PAK LAP BENNETT			Address: 112A DEPOT ROAD #25-119 SINGAPORE 101112		
ID Type / ID No.: NRIC NO / S8071677Z			Contact No.: Home/Office:		Mobile: 94364901
Nationality: SINGAPORE CITIZEN			Email: BENNETT.WONG@HOTMAIL.COM		
Sex: Male	Age: 41	Date of Birth: 09/11/1980	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales and marketing manager			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 07/02/2022 08:45	Type of Location: Straight Road
Location: HENDERSON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 20 Km/h	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SHB712Z	Car	TOYOTA	PRIUS	Maroon		0
SMW268U	Car	NISSAN	SERENA 1.2L HIGHWAY STAR PREMIUM E -POWER	Black		0



**SINGAPORE
POLICE FORCE**



T/20220207/7019

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3

Report No: T/20220207/7019

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMW268U	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00996165	15/01/2022	14/01/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WONG PAK LAP BENNETT	ID No.	S8071677Z
Related Vehicle	SMW268U (Car)	Contact No.	94364901
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

Incident happen at 7th Feb 2021 at 8:47am at Henderson Road toward Bukit Merah Junction before Jalan Bukit Merah.

I was driving on the extreme left lane of Henderson road (2 lane). there was traffic ahead waiting for change of traffic light. When the traffic light turn green, i accelerate slowly while Taxi from SMART - SHB 712Z swing the vehicle from extreme right lane to left lane from the side.

i sound the horn to incident my present but it was too late before the taxi hit the right side of SMW 268U.

I stopped the vehicle immediately after the collision which the driver drive additional 10 meter away. After collision, I had offer my particular to another party driver. The taxi driver had taken a photo of my driving license. when i requested for the particular from the driver of SHB 712Z. he refused and only mentioned to make insurance claims.

i had then inform him that at least provide taxi license for insurance claims but it was denied by the driver who drove off.

i am unable to determine if the driver having any valid driving license or any valid taxi license



**SINGAPORE
POLICE FORCE**



T12022020717019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T12022020717019

CONTINUATION OF REPORTSketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP18 /
IRMAN BIN MOHAMAD SAID
Contact No.: 65476145

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
07/02/2022 11:57

Classification Of Case:

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 677Z

Vehicle Details

Vehicle No.: SMW268U

Vehicle to be Exported: No

Intended Deregistration Date: 11 Feb 2022

Vehicle Make: NISSAN

Vehicle Model: SERENA 1.2L HIGHWAY STAR PREMIUM E-POWER

Primary Colour: Black

Manufacturing Year: 2020

Engine No.: HR12186197K

Chassis No.: JN1EBAC27Z0000612

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$29,949.00

Original Registration Date: 15 Jan 2021

First Registration Date: 15 Jan 2021

Transfer Count: 0

Actual ARF Paid: \$18,929.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jan 2031

PARF Rebate Amount: \$14,196.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$49,300.00

COE Rebate Amount: \$43,998.00

Total Rebate Amount: \$58,194.00

The information contained herein is correct as at 11 Feb 2022

OK

Nissan Serena e-POWER Hybrid 1.2A Highway Star Premium

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

THE AUTOMOTIVE GUYS

Price **\$141,900**

Depreciation ⓘ \$14,440 /yr
[View models with similar depre](#)

Reg Date 29-Mar-2021
(9yrs 1mth 14days COE left)

Mileage 6,000 km

Manufactured ⓘ 2020

Road Tax ⓘ \$802 /yr

Transmission Auto

Dereg Value ⓘ \$58,101 as of today (change)

Fuel Type Petrol-Electric

COE ⓘ \$47,001

OMV ⓘ \$30,937

Engine Cap 1,198 cc

ARF ⓘ \$20,312

Curb Weight ⓘ 1,758 kg

Power 100.0 kW (134 bhp)