

FBS4918C

TUAS BAY DRIVE

S/N	Qty	Description	(S\$)
Parts			
1	1pcs	Front Mudguard <i>x nn</i>	\$ 75.00
2	1pcs	Front Wheel Shaft <i>x nn</i>	\$ 130.00
3	1pcs	Front Wheel Bearing <i>x nn</i>	\$ 80.00
4	1pcs	Front Disc Rotor <i>x nn</i>	\$ 200.00
5	1pcs	Stem Steering <i>- rec</i>	\$ 165.00
6	1pcs	Handlebar <i>- BT</i>	\$ 80.00
7	1pcs	Clutch Lever <i>- CUT</i>	\$ 40.00
8	1pcs	Brake Lever <i>x nn</i>	\$ 40.00
9	2pcs	Balancer @25/pcs <i>(CLH) - CUT</i>	\$ 50.00
10	2pcs	Side Mirror @30/pcs <i>- BR</i>	\$ 60.00
11	1pcs	Front Headlamp Cover <i>x nn</i>	\$ 60.00
12	1pcs	Rear Headlamp Cover <i>x nn</i>	\$ 60.00
13	2pcs	Front Signal Lamp @25/pcs <i>x nn</i>	\$ 50.00
14	1pcs	Headlight Assy <i>x nn</i>	\$ 160.00
15	1pcs	Belly shield covering <i>x nn</i>	\$ 90.00
16	1pcs	Front Side Fairing LH <i>x nn</i>	\$ 95.00
17	1pcs	Front Side Fairing RH <i>x nn</i>	\$ 95.00
18	1pcs	Centre covering <i>x nn</i>	\$ 120.00
19	1pcs	Front Footrest Bar <i>- BT</i>	\$ 75.00
20	2pcs	Front Footrest Rubber @45/pcs <i>(CLH) CUT</i>	\$ 90.00
21	1pcs	Gear Padal <i>- BT</i>	\$ 50.00
22	1pcs	Brake Pedal <i>x nn</i>	\$ 80.00
23	1pcs	Rear LH Foot Rest <i>x nn</i>	\$ 45.00
24	1pcs	Rear LH Foot Rest Bracket <i>x nn</i>	\$ 80.00
25	1pcs	Exhaut pipe <i>x nn</i>	\$ 400.00
26	1pcs	Exhaut pipe cover <i>- CUT</i>	\$ 65.00

Total \$ 2,535.00
 -10% \$ 253.50
Parts Sub Total \$ 2,281.50

Special Nett			
27	1pcs	Front fork seal <i>+ nn</i>	\$ 80.00
28	1pcs	Front fork oil <i>x nn</i>	\$ 300.00
29	1pcs	Rear Box <i>- CUT</i>	\$ 350.00
30	1pcs	Rear Box Bracket <i>- BT</i>	\$ 150.00
31	1pcs	Lh Round Box <i>x nn</i>	\$ 120.00
32	1pcs	No. plate (front) <i>x nn</i>	\$ 20.00
33	1set	Body sticker <i>x nn</i>	\$ 180.00
34			

Total \$ 1,200.00

Labour

--	--

1	Towing	\$	100.00	60-
2	To realign body frame	\$	350.00	x
3	To R&R fornt suspension, handle bar, headlamp, side fairing, and attachments.	\$	400.00	250-
				310
		Labour Total: \$	850.00	
		Sub Total (labour and parts): \$	4,331.50	

Vehicle is at **5 Soon Lee Street #01-38 Pioneer Piont S(627607)**
Please arrange your surveyor to come down to survey the vehicle.
Contact : **Daryl 98356259**

Steve (LKK)
11/2/22
w/P, L/S
Resurvey After Spray
3 days

= 1254.50
L/S - 1003.60
= 1000

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--