

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

(SUPPLEMENTARY)INSURER: **India International Insurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MFL0003414_02	Date of Loss:	22/01/2022
Vehicle Reg. No.:	SNC470U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		
Driver:	KWOK MUN SENG		
Make/Model:	MAZDA 3, 1.5 4DR M-HYBRID CLASSIC (A)	Vehicle Reg. Date:	27/09/2021
Vehicle Colour:	METALLIC DARK BLUE		
Engine No:	P520757500	Chassis No:	JM6BP2SAAM1108709
Odometer:	5889 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

COST OF CLAIMS**Amount**

Parts	5,582.48
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	5,582.48
+ GST 7.00% (\$)	390.77
Nett Amount (\$)	5,973.25
+ Previous Estimates (\$)	35,683.25
Claim Total (\$)	41,656.50

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Apr 2022)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SNC470U/07/04/2022 08:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH FRT DOOR WEATHER STRIP torn	20.00	0.00	*96.60 FL
2	1		*LH WING MIRROR SIGNAL LAMP cracked	20.00	0.00	*124.30 FL
3	1		*PETROL UNIT CONVERTER RELAY BRACKET cracked	20.00	0.00	*140.10 FL
4	1		*HEADLAMP SIGNAL BULB SOCKET LH broken	20.00	0.00	*28.20 FL
5	1		*BONNET LOCK TOP COVER cracked	20.00	0.00	*19.10 FL
6	1		*LH FRT SHOCK ABSORBER TOP MOUNTING bent	20.00	0.00	*95.00 FL
7	1		*RH FRT FENDER STAY FRT bent	20.00	0.00	*66.40 FL
8	1		*FRT FENDER TOP RETAINER LH cracked	20.00	0.00	*46.10 FL
9	1		*WIRE HARNESS torn	20.00	0.00	*5,942.00 FL
10	1		*HEADLAMP HID UNIT LH dented	20.00	0.00	*420.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,978.10
- List Item Discount on L Items (\$\$)	1,395.62
Total Parts (\$\$)	5,582.48

ComfortDelGro Engineering Pte Ltd/SNC470U/07/04/2022 08:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SNC470U/07/04/2022 08:31 . Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >