



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Alex Sim
TEL. NO. : 6265-0026 / 98154748
EMAIL : alex@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : Evershine Projects Pte Ltd

DATE : 11-02-22

VEHICLE NO. : YN4061C
MODEL NO. : Isuzu
CHASSIS NO. : JAANMR85HD7101720
ENGINE NO. : 4JJ1369404
LTA REG DATE : 13-08-13

CLAIM TYPE : Third party claim
D.O.A : 09-02-22
CLAIM REF NO. : asm/AC22011/JL

Quotation for Accident Repair

S/N	SPARE PARTS (nett)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear wooden drop gate / BR	1	\$ 550.00	\$ 550.00 ✓
2	Front wooden panel / BR	1	\$ 550.00	\$ 550.00 ✓
3	Under cross beam ? x 111	2	\$ 180.00	\$ 360.00 ✓
4	Under long beam / BR	1	\$ 360.00	\$ 360.00 ✓
5	Cabin hook handle / BT	1	\$ 450.00	\$ 450.00 ✓
6				\$ -
SUB-TOTAL :			1910 ✓	\$ 2,270.00

LABOUR CHARGES

1	To remove wooden body deck, to replace broken wooden plank and drop gate, to knock and straighten body frame, realign wooden floor plank etc.	\$ 1,400.00	1000
2	To panel beat cabin rear end panel, replace cabin hook handle and realign cabin and door.	\$ 1,050.00	600
3	spray painting	\$ 400.00	300
TOTAL LABOUR : = 3810 ✓		\$ 2,850.00	

GRAND TOTAL : \$ 5,120.00

Steven (LKK)
14/2/22. 11-31c

ML RL
7 days
L/S
R/S
My RL y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Alex Sim
TEL. NO. : 6265-0026 / 98154748
EMAIL : alex@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : Evershine Projects Pte Ltd

DATE : 11-02-22

VEHICLE NO. : YN4061C
MODEL NO. : Isuzu
CHASSIS NO. : JAANMR85HD7101720
ENGINE NO. : 4JJ1369404
LTA REG DATE : 13-08-13

CLAIM TYPE : Third party claim
D.O.A : 09-02-22
CLAIM REF NO. : asm/AC22011/JL

Quotation for Accident Repair (supplementary)

S/N	SPARE PARTS (nett)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear Metal frame	1	\$ 1,800.00	\$ 1,800.00
2	Rear LH Mudguard	1	\$ 250.00	\$ 250.00
3	U bolts	3	\$ 90.00	\$ 270.00
4	Bolts seuring wooden plank to beam	9	\$ 10.00	\$ 90.00
				\$ -
SUB-TOTAL :				\$ 2,410.00

BT
BR
BT
nec

LABOUR CHARGES

- 1 To remove wooden deck and necessary attachments parts for knocking and straightening chassis. Welding and reinforce cracked chassis . Reinstallation . \$ 2,500.00

2000

TOTAL LABOUR : \$ 2,500.00

GRAND TOTAL : \$ 4,910.00