

NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43
 #07-97 Singapore 520436
 Tel: (65) 9674 1991
 ✉ nineteenautowerks@gmail.com



NINETEEN
AUTOWERKS

ESTIMATE

DATE: 14-Feb-22
 DOA: 10-Feb-22
 VEHICLE NO: SNA 9755 A
 MAKE & MODEL: KIA CERATO

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
LIST ITEMS			
Rear Bootlid <i>bl/</i>	1	\$893.80	\$893.80 ✓
Rear Boot Lamps <i>xan</i>	2	\$383.00	\$766.00 X
Rear Boot Inner Lock <i>xan</i>	1	\$146.50	\$146.50 X
Rear Boot Rubber <i>xan</i>	1	\$148.60	\$148.60 X
Rear Boot "KIA" emblem <i>new</i>	1	\$52.50	\$52.50 ✓
Rear Boot "Cerato" emblem <i>new</i>	1	\$42.50	\$42.50 ✓
Rear Taillamps <i>LH X/RH - 2ea/</i>	2 <i>1pc</i>	\$575.20	\$1,150.40 <i>575.20</i>
Rear End Panel <i>repair</i>	1	\$698.50	\$698.50 X <i>R</i>
Rear End Panel Inner Garnish <i>xan</i>	1	\$182.50	\$182.50 X
Rear Smart Keyless Sensor <i>xan</i>	1	\$225.50	\$225.50 X
Rear Bumper <i>ca/</i>	1	\$858.00	\$858.00 <i>651</i>
Rear Bumper Inner Sponge <i>? xan</i>	1	\$185.50	\$185.50 X
Rear Bumper Reflectors <i>? LH X/RH - 2ea/</i>	2 <i>1pc</i>	\$198.00	\$396.00 <i>198</i>
Rear Bumper Reinforcement <i>2ea/</i>	1	\$376.00	\$376.00 <i>318</i>
Rear Bumper Reinforcement Stays <i>? xan</i>	1	\$345.00	\$345.00 X
Rear Bumper Reinforcement Brackets <i>? xan</i>	1	\$88.70	\$88.70 X
Rear Bumper Side Retainers <i>LH X/RH - 2ea/</i>	2 <i>1pc</i>	\$45.50	\$91.00 <i>45.50</i>
Rear Diffuser <i>ca/</i>	1	\$320.90	\$320.90 ✓
Rear Diffuser Garnish <i>xan</i>	1	\$156.10	\$156.10 X
		Total	\$7,124.00
		Less 20%	\$1,424.80
			\$5,699.20

3097.40
20%
2477.92

SPECIAL NETT ITEMS

Sundries <i>ca/</i>	1		
Rear Bumper Clips (set) <i>ca/</i>	1		
Rear End Panel Clips (set) <i>xan</i>	1		
Rear Reverse Sensor (set) <i>? xan nw/</i>	1		
Rear Reverse Camera <i>xan</i>	1		
			<i>250</i> { <i>20</i> \$60.00
			<i>30</i> \$100.00
			<i>100.00</i> X
			<i>200</i> \$350.00
			\$350.00 X
			\$960.00
Parts Total			\$6,659.20

LABOUR CHARGES

Remove & Refit Damaged lamps, wiring	\$80.00	<i>30</i>
Remove & Refit Inner Garnish	\$150.00	<i>60</i>
Remove & Refit Rear reverse sensor & camera	\$250.00	<i>60</i>
Transfer Bootlid mechanism and wiring assembly	\$120.00	<i>60</i>
To apply undercoating for rust roofing	\$180.00	<i>40</i>

Panel Beating
Spray Painting

Labour Total

Total Parts and Labour Cost of Repair

1450	500	\$1,800.00
	700	\$1,500.00
		\$4,080.00
		\$10,739.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Russell

Ap 90010068

5 days

~~4/5~~

11/02/22 @ 1620

after
Resurvey ~~before~~ paint

2477.92

250.00

1450.00

4177.92

202

3342.33

4/5 - 3,350