

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S0M02YBJ Date: 08<sup>th</sup> Mar 2022

Our Ref: CS3/ASM20013508/Gqy3e2-1

## M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Stacey Ng

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 3451P INSURED VEHICLE: SJB 3782C ACCIDENT DATE: 07/12/2020

We thank you for your instruction on 11/02/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 3451P from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement and Police Report of Vehicles SLA 3451P.
- c) Final Repair Bill of SLA 3451P from M/s Garage 13 Pte Ltd.
- d) Colour damaged vehicle photographs of SLA 3451P.

Pre-Repair Inspection Date: 08/12/2020 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLA 3451P

Make & Model : Toyota Estima Aeras 2.4 A

Year of Registration : 2016

Chassis Number : ACR507126872

Engine Capacity : 2362 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.