| (08/11/13) wef ASS. REC. BY: Marcus  REF: CS/SMC | 22001388/4473   |
|--|---|
| 1  | SIGNMENT  |
| From: Date:                                      | Veh No: 6BK 3394L Yr Regn: 10/11/14   |
| OD / TP TWS / TP RES / OD RES / EVA / INV / MV   | Type: M.Car / M.Cycle / Bus (Van / Lorry / Taxi / Prime Mover /             |
|  | Truck / Trailer or (M)  |
| 0.75/40  | Make: Toyota hiace c.c 2982   |
| 1300 (7)   | Colour white A/C: Insured / Std / NI / NA                                   |
| CS SENER CIESCEN                                 | Sp.Reading 196961 T/Radio: Insured / Std / NI / NA                          |
| Insured: S6Z 20 X                                | Lilg/NO.  |
| Policy No. Claims No.                            | Gen. Cond. Good / Fair / Poor / Burnt                                       |
| Sum Insured: Excess:                             | Steering: Iporder / Jammed / Leaked / Burnt or                              |
| (Client's Record)                                | Brake: Inorder / Jammed / Leaked / Burnt or                                 |
| Make of Veh:                                     | Modi: Nij / S/Rim / STD A/Rim or  |
|  | Tyre Size: F: 195/fon/f   |
| (Policy Condition)                               | R:  |
| Remark: The veh had commenced its N/S O/S        | ^   |
| repair at the time of inspection.                | BS /DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or |
| Bal. or Market Value:                            | French  |
| IDAC Accident Rport: Consistent? : Yes or No     | DID-I   |
| GIA / PR Seen: Consistent?: Yes or No            | IIIIII IVDai. mm  |
| Est. Repairs: days Res.: Yes or No               | DOA GARAGE  |
| Lum Sum: 3 Val.: Yes or No                       | 1.1100 0.01. 13/1/27  |
| 70 VAII. 103 01 NO                               | Survey held at  |
| CA / REV / REP. / 24 HRS C OF L                  | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or                 |
| Date: Person Contacted: PF-FVehicle: IN / OUT    | Reer 0/5.   |
| Date / Time Action / Instruction L7A \$ 13643    | The U/C / Chassis frame / Body Structure affected due to collision.         |
| Red lok MS Con                                   |   |
| 110 11 000                                       |   |
| 24/12 2/5 \$ 3800 informed Sa                    |   |
| red: 5602.05;59%                                 |   |
| Ted. 3002.03,39 /6                               |   |
|  |   |
|  |   |
|  |   |
| Date/Time, File Pass to? : Preli. Report Da      | ays Of Repair: 5  |
| 1) : Final Report Re                             | esurvey No. of Trip: Survey Fee:  |
| Date/Time, File Return to?                       | Transportation:   |
| 2) Add Fee:                                      | : Site Insp (\$ )S+RS,SI  |
|  | : Interview (\$ ) Photos  |
| Report Format :                                  | : Tech. Invs (\$ ) Others   |
| Lump Sum / I.B.I: (\$                            | :Weekend (\$  |
|  | TOTAL   |
|  |   |

|        |   | ADJUSTMENT C   | ollowing:                              |                |         |                     | 2/5413000                    |
|--------|---|--|--|----------------|---------|---------------------|------------------------------|
|        | e No: GBK3394L  | <ul> <li>To resurvey before/after</li> <li>To display damaged par</li> </ul> | spray painting<br>t(s) during resurvey | Report No      | : SA1N  | 1222B0001_11-02-2   | 022_175558 Sday F            |
|        | s No: JTFHT02P700152  | 160 Parts prices are subject   | a "Without Prejudice" bas              | is: _          | 15/2/   | (2022               | vit Authorsal                |
|        | No: 1KD2453788  | <ul> <li>No illegal modification(s</li> </ul>                                | s) is allowed                          |                | : 15/2/ | 2022                | Lineison                     |
| MAKE:  | TOYOTA<br>L:/TOYOTA HIACE VAN TU  | Supplementary item(s)  | must be resurveyed and                 | TYPE           | · COM   | MERCIAL             | mercus                       |
| Poplar | cement of Damaged Pa  | is subject to hirar appro  | vai from insurance compa               | iny            |         |                     | oreicus                      |
| керіа  | cement of Damageu Fa  | Acknowledged by Repair<br>Signature:   | er                                     |                |         |                     | 9009660 \$                   |
| S/No.  |   | Description  |  | Qty            | Our     | Recommendation 2    | 15/1/2 2<br>hepholoffluileja |
|        | T- 111-   | 1900   | 2000                                   | 1              | \$      | 2,162.70            |                              |
|        | Tailgate  |  | Nel                                    | 1              | \$      | 371.85              |                              |
|        | Tailgate emblem   | TP68:10  |  | 1              | \$      | 381.30              |                              |
|        | Rear bumper   |  | Torn                                   | 1              | \$      | 151.45              |                              |
|        | Rear bumper bracket RH  |  | 0                                      | 1              | \$      | 182.45              |                              |
|        | Rear bumper side retain   | erkh   | Cu                                     | 1              | \$      | 371.75              |                              |
|        | End panel outer   | 2// 12   | ND                                     | 1              |         | 381.90              |                              |
|        | Tail lamp RH  | 366.10   | 1500                                   | 1              | \$ (    | 271.75              |                              |
|        | Tail lamp lower garnish I   |  | DIS                                    |                | _       |                     | V                            |
|        | Tail lamp lower garnish b   | oracket RH   | 2                                      | 1              | \$      | 174.45              | 2                            |
|        | Tail lamp fender RH   |  | K                                      | 1              | \$      | 1,712.45            | s/n                          |
| 11     | 1-set Reverse sensor  |  | Short                                  | 1              | \$      | 200.00              | 100                          |
|        |   |  |  |                | \$      | 6,362.05            |                              |
|        |   |  |  |                |         |                     |                              |
|        |   |  |  | Total (Parts): | \$      | 6,362.05            |                              |
|        |   |  |  |                |         |                     |                              |
| Labou  | r Charges   |  |  |                |         | 150.00              | 10-                          |
| *      | To remove and transfer  | /reinstate the rear wir  | ndscreen                               |                | \$      | 150.00              | 100                          |
| *      | Rear windscreen sealant   | t .  |  |                | \$      | ner 50.00           | 100<br>40 S/N                |
| *      | To dismantle and renew  |  | gate fittings, wiper                   |                | \$      | 150.00              | 60                           |
|        | motor to the new tail ga  | te, re-set of same.  |  |                |         |                     |                              |
| *      | To dismantle and renew  | v the reverse sensor in  | cluding re-set of sa                   | me.            | \$      | 80.00               | 40                           |
| *      | To dismantle and replace heat/weld, cut-off the elincluding knocking, repa      | nd panel inner, end pa   | nel outer, fender,                     |                | \$      | 1,250.00            | 900                          |
| *      | To putty and spray paint<br>bumper, tail lamp lower<br>including knocking, repa | garnish, end panel ou  | ter, fender RH,                        |                | \$      | 1,200.00            | 650                          |
| *      | To apply rustproofing o fender RH.  | n the repaired and rep   | placed tailgate and                    |                | \$      | 150.00<br>Aec 10.00 | 60                           |
| *      | Sticker 70km/h  |  |  |                | \$      | Nec 10.00           | s/NV                         |
|        |   | 2.2717.34  |  | Total Labou    | r: \$   | 3,040.00            |                              |
|        |   | 252  |  |                | 41-2-2  |                     |                              |
|        | Subtotal  | 1  |  |                | \$      | 9,402.05            |                              |
|        | Gst 7%  | 9.2720 ST<br>5.N-250   |  |                | \$      | 658.14              |                              |
|        | Total cost of repairs (   | Total cost of parts +  | Total Labour Cost                      | :):            | \$      | 10,060.19           |                              |
|        | . sta. cost of repairs (  |  | 46047                                  |                |         |                     |                              |

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars                        |                                    |  |
|--|------------------------------------|--|
| Owner ID Type:                                   | Company                            |  |
| Owner ID:  | 082Z                               |  |
| Vehicle Details                                  | GBK3394L                           |  |
| Vehicle No.:                                     | No                                 |  |
| Vehicle to be Exported:                          | 15 Feb 2022                        |  |
| Intended Deregistration Date:                    |                                    |  |
| Vehicle Make:                                    | TOYOTA                             |  |
| Vehicle Model:                                   | TOYOTA HIACE VAN TURBO 5 DR MANUAL |  |
| Primary Colour:                                  | White                              |  |
| Manufacturing Year:                              | 2014                               |  |
| Engine No.:                                      | 1KD2453788                         |  |
| Chassis No.:                                     | JTFHT02P700152160                  |  |
| Maximum Power Output:                            | •                                  |  |
| Open Market Value:                               | \$27,502.00                        |  |
| Original Registration Date:                      | 10 Nov 2014                        |  |
| First Registration Date:                         | 10 Nov 2014                        |  |
| Transfer Count:                                  | 2                                  |  |
| Actual ARF Paid:<br>Intended PARF Rebate Details | \$1,376.00                         |  |
| PARF Eligibility:                                | No                                 |  |
| PARF Eligibility Expiry Date:                    | •                                  |  |
| PARF Rebate Amount: Intended COE Rebate Details  | \$0.00                             |  |
| COE Expiry Date:                                 | 09 Nov 2024                        |  |
| COE Category:                                    | C - Goods Vehicle & Bus            |  |
| COE Period(Years):                               | 10                                 |  |
| OP Paid:   | \$49,889.00                        |  |
| COE Rebate Amount:                               | \$13,643.00                        |  |
| Total Rebate Amount:                             | \$13,643.00                        |  |

The information contained herein is correct as at 15 Feb 2022  $\,$ 

## SGCARMART.COM

Login Sign up

New Cars

**Used Cars** 

Rental Cars

Sell My Car

Directory

**Products** 

Insurance

Articles

Resources





\$2700/mth BMW 4 Series 420i Coupe Sport



Mazda 6 2.0A Executive With 1 Owner.

\$330/wk Toyota Vios 1.5A



Rental starts from \$2000/mth Audi A4 1.8A

Forum

Post an Advertisement Sell it yourself! Advertise it at just

\$68 until it's SOLD!



Full Agent Service Warranty Oct 2023, Help Submit Loan 1.88% To Belie

Direct Owner



Browse by Category

Post an Ad

6 vehicles



toyota hiace

Sort by Date Posted



✓ 20 results/page Search

Advertiser Login

Model

Ways of Selling

Price

Anv

\$35,800

Depreciation

Reg Date

Eng Cap

Anv

2.982 cc

Mileage

Veh Type

Search Selection

tovota hiace

GL

Anv

2014

Anv

Any

Bus

Available Available

Fuel Type: Diesel

Think One Automobile & Trading

Tovota Hiace Commuter 3.0A

Posted: 04-Feb-2022 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace

PREMIUM AD



Toyota Hiace Commuter 3.0A GL

\$33,000

\$12,640 /yr

\$12,720 /vr

26-Sep-2014

09-Dec-2014

2,982 cc

Available

Fuel Type: Diesel

13 Seater Euro 5 Hiace Commuter 3.0A. Resprayed To Pearl White. Plate No Will Be Retained. Fully Serviced, Wear And Tear Replaced. Original Condition And Well Maintained, Full Loan Available, Whatsapp To Arrange For Viewing.

DIRECT OWNER

Posted: 30-Jan-2022 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace

\$33,800

Available

**GL High Roof** 

Toyota Hiace Commuter 3.0A

30-Sep-2014

2,982 cc

PREMIUM AD

Fuel Type: Diesel

Well Maintained 13 Seater Euro 5 Hiace Commuter. Incredible Performance Coupled With Good Fuel Economy From The Diesel Engine. Fully Suitable For Everyday Usage With Low To No Maintenance. Pristine Condition Van, Well Taken Care By Previous Owner. Flexible Fin...

Posted: 26-Jan-2022 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace

Posted: 19-Jan-2022 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 3.0M

\$33,888

\$12,800 /yr

09-Oct-2014

2,982 cc

Van

Available

PREMIUM AD

Fuel Type: Diesel Best Deal In The Market! 1 Private Owner Only! No.1 Most Reliable Japanese 5 Door Diesel Van! Low Fuel Consumption And Extremely

Low Maintenance Cost! Ideal For All Business Usage! Powerful Workhorse! Monthly Only Start From \$700+! Cheaper Then Rental Cost! \$...



Lenovo 10.1" QLED 4G Android Car Player @\$599

Upgrade your infotainment and gain access to Google map, Waze, Youtube, Netflix, Spotify and podcast.

Find out more!



Toyota Hiace 3.0A

\$34,800

\$14,860 /yr

20-Jun-2014

2,982 cc

120,000 km


Van

Available

Fuel Type: Diesel

Rare. Super Lower Mileage. One Careful Owner. Under Utilized. No Repair Needed. Rd Tax Expire 19/06/2022. Loan / Trade In Available. Call Now. Before It Gone. Viewing By Appointment Only.

Posted: 04-Jan-2022 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 3.0M

\$31,800

\$13,090 /yr

22-Jul-2014

2.982 cc

161,000 km

Available

Van In Tip Top Condition Inside Out, Newly Replaced Clutch Assembly, Just Serviced, No Other Repairs Needed, View To Believe, Low Down Payment, Various Loan Options Available To Suit Your Budget.

Posted: 29-Dec-2021 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace

Save this search criteria, to get email alerts whenever a match is found.