

⏪

⏩

1 of 2 ?

⏮

⏭

100% ▾

📄 ▾

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD			Ref: CS/AIS22001391/Aqf3	
79 ROBINSON ROAD			Date: 14/02/2022	
#09-01 SINGAPORE 068897			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 8426Y	Veh. Inspected	SLM 1271S	
Policy No.		Coverage (\$)	0.00	
Claim No.	800SWAISCL2022 0058/SL-	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	14/02/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/02/2022	Inspection Date	14/02/2022	
Survey held at	1 Kaki Bukit Ave 6, #01-15 AutoBay @ Kaki Bukit			
Repairer	POLYMATH GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				