

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Parts price revised and Supplementary

Vehicle number: SJN9416H

Make & Model: Hyundai Avante

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey
21/2/2022
1312 hrs
Taim Lin

No.	Description of spare parts	Qty	Amount
1	RH rear door	1	\$ 1,095.00
2	RH rear door lock	1	\$ 295.00
3	RH rear door inner trim board	1	\$ 685.00
4	RH rear door frame black sticker	1	\$ 45.00
5	Bootlid inner trim	1	\$ 153.00
6	RH rear fender inner panel	1	\$ 480.00 783.00
		Total	\$ 3,056.00
		Less 20%	\$ 611.20
		Total	\$ 2,444.80

DD✓
JM✓
NDX
NEC✓
NNX
DD✓

No.	Description of spare parts (Special Nett)	Qty	Amount
1	Bootlid spoiler	1	\$ 360.00 900.00
2	RH rear fender inner panel joint sealant	1	\$ 30.00 70.00

DL✓
NEC✓

No.	Labour		Amount
	Labour charges for supplementary		\$ 1,000.00
	Remove and replace RH rear door inner components to new door	80.00	\$ 150.00
	Spray painting	200.00	\$ 800.00

NNX