

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : ZAHARIN BIN ABUZAR  
 588A ANG MO KIO ST 52  
 #04-207  
 SINGAPORE 561588

Estimate No: MCI902469  
 Date: 14 Feb 2022  
 Policy No: P10423112R00  
 Veh Reg No: SJD5756E  
 Make/Model: TOYOTA RUSH 1.5X A

ATTN:  
 Your Ref No: SJD5756E  
 Claim Type: Third Party  
 Accident Date: 06/02/2022  
 TP Veh Reg No: SKL9193Z

## Estimate Repair Cost to Vehicle No :SJD5756E

Description	Quantity	List Price S\$	Amount S\$
<b>SPARE PARTS</b>			
1 TAILGATE	1 PC	841.90	
2 TAILGATE RUSH LOGO	1 PC	92.70	
3 TAILGATE RUBBER	1 PC	270.90	
4 TAILGATE INNER LOCK	1 PC	217.60	
5 TAILGATE INNER TRIMBOARD	1 PC	489.70	
6 TAILGATE SPARE WHEEL COVER OUTER	1 PC	1,704.80	
7 TAILGATE SPARE WHEEL COVER INNER	1 PC	335.70	
8 TAILGATE SPARE WHEEL COVER LOCK LH & RH	2 PC	540.20	
9 REAR BUMPER	1 PC	880.80	
10 REAR BUMPER SIDE RETIANER LH & RH	2 PC	140.20	
11 REAR BUMPER CLIPS	15 PC	82.50	
12 REAR BUMPER TOW COVER RH	1 PC	45.10	
13 REAR END PANEL	1 PC	317.80	
14 REAR END PANEL TOP GARNISH	1 PC	127.60	
		6,087.50	
	Less 25%	1,521.88	4,565.63
<b>Special Nett</b>			
15 NUMBER PLATE	1 PC	35.00	
16 REVERSE SENSOR	1 SET	200.00	
17 INNER SEAL	1 PC	20.00	
18 WINDSCREEN SEALANT	1 PC	40.00	
19 SPARE TYRE - CHECK PRICE	1 PC	0.0000	
		295.00	295.00
<b>LABOUR</b>			
20 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
21 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
23 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL. TO KNOCK & REPAIR FLOOR PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
24 TO SPRAY TAILGATE,SPARE TYRE COVER,REAR BUMPER,END PANEL,FLOOR PANEL.	1 PC	800.00	
		1,840.00	1,840.00

  
 Ah Lim Motor Company

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : ZAHARIN BIN ABUZAR  
588A ANG MO KIO ST 52  
#04-207  
SINGAPORE 561588

Estimate No: MC1902469  
Date: 14 Feb 2022  
Policy No: P10423112R00  
Veh Reg No: SJD5756E  
Make/Model: TOYOTA RUSH 1.5X A

ATTN:  
Your Ref No: SJD5756E  
Claim Type: Third Party  
Accident Date: 06/02/2022  
TP Veh Reg No: SKL9193Z

## Estimate Repair Cost to Vehicle No :SJD5756E

Description	Quantity	List Price	Amount
		<b>S\$</b>	<b>S\$</b>
		Total	S\$ 6,700.63
		Add GST @ 7%	469.04
		Total Amount Payable	S\$ 7,169.67

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED SIXTY NINE AND CENTS SIXTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY

Ah Lim Company

AUTHORISED SIGNATURE

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 478H

### Vehicle Details

Vehicle No.: SJD5756E  
Vehicle to be Exported: No  
Intended Deregistration Date: 11 Feb 2022  
Vehicle Make: TOYOTA  
Vehicle Model: RUSH 1.5X A  
Primary Colour: White  
Manufacturing Year: 2008  
Engine No.: 3SZ2062079  
Chassis No.: J200E0020315  
Maximum Power Output: 80.0 kW (107 bhp)  
Open Market Value: \$14,661.00  
Original Registration Date: 27 Mar 2008  
First Registration Date: 27 Mar 2008  
Transfer Count: 2  
Actual ARF Paid: \$14,661.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 26 Mar 2023  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$19,637.00  
COE Rebate Amount: \$4,413.00  
**Total Rebate Amount: \$4,413.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Feb 2022

OK