

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

11/02/2022

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SLG9228Y

Veh Model :- HONDA FIT 1.3G A

Estimate# :- CK422863

Claim # :-

ACC. Date :- 10/02/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	TAILGATE	1	PC	771.50
2.	TAILGATE GLASS MOULDINGS	1	PC	74.00
3.	TAILGATE EMBLEM - FIT	1	PC	35.00
4.	TAILGATE LOCK	1	PC	189.50
5.	TAILGATE WEATHERSTRIP	1	PC	92.30
6.	TAILGATE INNER TRIM	1	PC	100.70
7.	TAILLAMP ASSY LH	1	PC	206.80
8.	REAR FENDER LH	1	PC	652.40
9.	REAR END PANEL	1	PC	765.50
10.	REAR END PANEL TOP GARNISH	1	PC	62.80
11.	REAR BUMPER	1	PC	497.40
12.	REAR BUMPER RETAINER LH	1	PC	16.80
13.	REAR BUMPER CLIPS	1	PC	3.90
14.	REAR CHASSIS MEMBER LH (REPAIR)	1	PC	
15.	SPARE WHEEL PANEL (REPAIR)	1	PC	
16.	REAR FENDER INNER TRIM LH (CHECK)	1	PC	

LIST TOTAL S\$

20% DISCOUNT S\$

SPECIAL NET ITEMS :

1.	TAILGATE GLASS SEALANT	1	PC	40.00
2.	REAR QUATER GLASS SEALANT LH	1	PC	40.00
3.	REAR NUMBER PLATE	1	PC	40.00

SPECIAL NET TOTAL S\$

LABOUR :

TO CUT/ WELD REAR FENDER LH, REAR END PANEL.
KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER LH,
SPARE WHEEL PANEL. REMOVE AND REPLACE
ACCIDENT DAMAGED PARTS. REALIGN ALL
CONNECTION.

SPRAY PAINT TAILGATE, REAR FENDER LH, REAR
CHASSIS MEMBER LH, SPARE WHEEL PANEL, REAR
END PANEL, REAR BUMPER

REMOVE & REPLACE TAILGATE GLASS AND CHECK
WATER LEAKAGE

REMOVE & REPLACE TAILGATE INNER TRIM,
MECHANISM AND CHECK LOCKING SYSTEM

REMOVE & REPLACE REAR QUATER GLASS AND
CHECK WATER LEAKAGE

REMOVE & REPLACE REAR SEAT ASSY. REAR FENDER

2302.10
-20%
1841.68

70

1090 900

899

50

30

X

1,200.00

1,000.00

120.00

60.00

100.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

11/02/2022

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 143787
Veh # :- SLG9228Y
Veh Model :- HONDA FIT 1.3G A
Estimate# :- CK422863
Claim # :-
ACC. Date :- 10/02/22
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TRIM, COVERING, FLOOR CARPET, UPHOLSTERY	1940		30 160.00
	REMOVE & REPLACE PETROL TANK, HOSE, GARNISH	=3851.68		X 80.00
	TO APPLY SEAL ON WELDING JOINTS	L/S - 3081.34		X 100.00
	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE	= 3100		X 280.00
	RUST PROOF AFFECTED AREA			30 100.00
	LABOUR TOTAL S\$			3,200.00

E. & O.E

[Signature]

NON-TAX AMOUNT S

AMOUNT S\$

6,122.96

GST @ 7 %

428.61

AMOUNT DUE S\$

6,551.57

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Steve (LKK)
15/2/22 10:30

[Handwritten initials and notes]
ML R
L/S
My PL G
5 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: