



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001425/Tqf3e2	
			Date: 01/06/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1141P	Veh. Inspected	SJV 9187B
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/22/2024	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	15/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	KNAFW612MA5198100	Colour	RED
	Odometer	158318 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	TOURADOR	6 mm
	L/H Front Tyre	225/45 R17	TOURADOR	6 mm
	R/H Rear Tyre	225/45 R17	TOURADOR	6 mm
	L/H Rear Tyre	225/45 R17	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/02/2022	Inspection Date	15/02/2022
	Survey held at	56 LOYANG WAY #04-04		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	