

15/2/22

MBL 9859

(TP-Polic) - To wing - \$45 - (Towing) / nec (labour)

Front Fork Repack \$150 - 100 / (labour)

Front Mudguard - \$78 - / BR

Front No Plate - \$30 - / nec

Brake lever (R) - \$28 - / cut

Mirror R/L \$58 - / cut 29 / (RH)

Handle Bar - \$98 - / BT

Seatcase R/L \$48 - / MIS 35 /

Handle Grip - \$38 - / TN 30 /

Head light Assy \$185 - / cut

Head cowl - \$78 - / cut

Front Fork cover \$76 - (RH) / BR 30 /

R/L Front Side Failing - \$170 - / cut

Brake Pedal - \$78 - / BT

Assy Front Foot Rest Bar \$95 - / BT

Air Pipe Pull Stem \$295 - / RD

R/L Rear Foot Bracket \$150 - / BR

Rear Foot Rest R/L \$48 - / cut 40 /

R/L Rear Side Side Cover \$180 - / cut 150 /

RM
(Absorber)
Rear Katong Assy - \$180 - / RT 150

Rear Seat Bar - \$78 - / CUT

labuan - \$180 150 / (labar)

P-1827
-10%
1644.30

~~2366~~

L-295
1939.30

L/S-1551.44
=1550

Steve (LKK)
16/2/22, 11.40a
83228813

MR RL
3 djs
L/S
M ALdy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

INVOICE

NO: I-203708/0030

SHING MOTORS & TRADING