

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ▼	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref: CS3/GRB22000619/Evf3-1		
64 CECIL STREET		Date: 15/02/2022		
#05-02 IOB BUILDING SINGAPORE 049711		Code: GRB		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 2895T	Veh. Inspected	SLN 4090Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	MFL2022D0000295	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	15/02/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2022	Inspection Date	16/02/2022	
Survey held at	ENG HUP AUTOPARTS ACCESSORIES CO. 387J BLK 1 WOODLANDS ROAD SINGAPORE 677899			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				