

(08/11/13)

ASS. REC. BY:

REF

CS6/AIS22001460/Gcy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA7702 R Yr Regn: 12/7/2021Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.5X C.C. 1496Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 11379 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI 1327494Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R15

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____

D.O.I. _____

Survey held at DesktopDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/6/23	Finalised final sig @ 7,548.40; 5 days with Kelly. (Red 632p, 82)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: OD DesktopLump Sum / (B.I.) (\$ 7,548.40)

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: Allianz Global Corporate & Specialty SE, Singapore Branch

SP2000438618

Policy No:

10.02.2022

Date:

Accident Date : 08.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R			
1pc	Bonnet / <i>due</i>		380.00 ✓
1pc	Bonnet Center Rubber Seal / <i>twi</i>		15.00 ✓
1pc	Bonnet Lock / <i>ht</i>		65.00 ✓
1pc	Grille / <i>CRA</i>		180.00 ✓
1pc	Grille Emblem / <i>MC</i>		15.00 ✓
1pc	Grille Top Chrome Garnish / <i>CRA</i>		160.00 ✓
1pc	Grille Bracket (Center) ✓ BR		45.00 ✓
2pcs	Grille Brackets (Side) ✓ BR		19.00 ✓
1pc	Front Bumper / <i>DR</i>		180.00 ✓
12pcs	Front Bumper Clips / <i>MC</i>	1.50	18.00 ✓
1pc	Front Bumper Reinforcement ✓ BT		180.00 ✓
2pcs	Front Bumper Top Retainers ✓ BR	42.00	84.00 ✓
1pc	Front Bumper Center Air Grille ✓ BR		65.00 ✓
1pc	Front Bumper Lower Lip ✓ CUT		120.00 ✓
1pc	Front Bumper Fog Lamp ✓ BR		120.00 ✓
1pc	Front Bumper Fog Lamp Cover ✓ CUT		20.00 ✓
2pcs	Front Bumper Corner Retainers ✓ BR	10.00	20.00 ✓
2pcs	Headlamps (LED) ✓ BR	850.00	1,700.00 ✓
1pc	Radiator ✓ CUT		480.00 ✓
1pc	Air Con Condenser ✓ BT		400.00 ✓
1pc	Air Con Condenser Side Air Guide ✓ CRA		28.00 ✓
1pc	Front Windscreen Glass / <i>scr</i>		1,000.00 ✓
1pc	Front Windscreen Glass Moulding / <i>MC</i>		100.00 ✓
	Cost Plus 10%		5,394.00
			539.40
			5,933.40 ✓
	Front Number Plate / <i>ht</i>		45.00 SN ✓
	Front Windscreen Glass Sealant / <i>MC</i>		25.00 SN ✓
	Front Windscreen Glass Fastener / <i>MC</i>		12.00 SN ✓
	Front Windscreen Glass IU Bracket / <i>MC</i>		180.00 SN
	Front Windscreen Glass Solar Heat Film ? X nn		70.00 SN
	Front Windscreen Glass Shade Film ? X nn		
	To Conduct Electrical Check, Focus Headlamp		30.00 ✓
	To Dismantle Replace Front Windscreen		100.00 ✓

C/F

6,395.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SP2000438618

Date: 10.02.2022

Accident Date : 08.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R		
	To Remove / Refit Air Con Condenser & Refill Air Con Gas	B/F	6,395.40
	Labour Charge - Panel Beating, Repairing Front Chassis Member, Inner Panel, Support Panel, Front N/S Fender And Part Replacement		120.00 ✓
	To Respray Affected Areas		700.00 500
		1350	800.00 600
		Total :	8,015.40
			8180.40
			7383.40
			supp - 165
			P/P - 7548.40

Guo Bianq.
Partly Part
No Authorize
5 days

Access TBA

UKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

By Repairer

趙 源 摩 哆

Chew Goon Motor

新加坡宏茂橋第 2A 工業區第五道大牌十號門牌十五,十六,十七(一樓)及門牌五(三樓)

Blk 10 Ang Mo Kio Industrial Park 2A, Ave 5

#01-15, 16 & 17 AMK Autopoint, Singapore 568047

Business Reg. No. : 221880/00C GST Reg. No. : MX-0486007-AO

Tel : 6484 1626 (24 Hrs) Fax : 6484 0465

E-mail : chewgoon@singnet.com.sg

◀ 修理各种汽车打吗咭喷漆等 ▶

Allianz Global Corporate & Specialty SE, Singapore Branch

Accident Date : 08.02.2022

21.02.2022

Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R

Supplementary

1pc	Front Grille Top Retainer Beam	✓	BR	95.00	✓
1pc	Air Cleaner Cold Air Intake Duct	✓	CRA	55.00	✓
				150.00	
	Cost 10%			15.00	
			Grand Total :	165.00	✓