

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD 10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Ref: CS/ICS22001466/Kqf3 Date: 15/02/2022 Code: ICS		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SGK 8671U	
Policy No.	MPC21P00174500	Coverage (\$)	0.00	
Claim No.	DMPC2200063H	Excess (\$)	0.00	
Assign From	MERIMEN (LIU CHUN CHEONG)	Assign Date	15/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/02/2022	Inspection Date	16/02/2022	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				